

TACAN RWY 32

TACAN BKF
Chan 33

APCH CRS
328°

Rwy ldg 11,006
TDZE 5663
Arprt Elev 5663

AL-538 [USAF]

BUCKLEY SFB (KBKF)

⚠ * When ALS inop, increase CAT AB RVR to 55 and vis to 1 mile, CAT CDE vis to 1¾ miles.
** Circling NA east of Rwy 14-32.

ALSF-1
A1

MISSED APPROACH: Climbing right turn to 8200 and intercept BKF TACAN R-148 direct BEKEE and hold or as directed by ATC.

ATIS ★
119.675 259.3

DENVER APP CON
128.45 251.075

TOWER ★
121.0 291.675

GND CON
121.6 275.8

CLNC DEL
121.6 275.8

Missed approach requires use of RNAV or ATC RADAR monitoring.

BUCKLEY
Chan 33 BKF

CAT E remain within 4.25 NM of Rwy when circling.

5958
6070
5904
LASTE BKF 4
6074
MUSOE BKF 6.5
RADAR
6525
6566
5791
6058
7048
HOLD 10,000 8200
(IF) BEKEE BKF 13
(IAF) DERYL BKF 16
R-148
148°
328°

MSA BKF 2.5 NM
7600
10,800
9600
125°
030°
300°

EMERG SAFE ALT 100 NM 16,500

8200
BEKEE BKF 13
BKF R-148

TACAN
CENAR 1.7
3
LASTE 4
MUSOE 6.5
RADAR
BEKEE 13
DERYL 16
8100
8000
7400
328°
3.02°
TCH 45
0.5 NM
2.3 NM
2.5 NM

ELEV 5663
TDZE 5663

5714
5846
5732
5694
5708
5614
5700
TWR
11,006 x 150
32
328° to TACAN
HIRL Rwy 14-32
REIL Rwy 14

SW-1, 27 NOV 2025 to 25 DEC 2025

SW-1, 27 NOV 2025 to 25 DEC 2025

AURORA, COLORADO
Amdt 3 27APR17

39°42'N-104°45'W

BUCKLEY SFB (KBKF)

TACAN RWY 32