

ILS RWY 11 (CAT II & III)
WORCESTER RGNL (ORH)

MISSED APPROACH: Climb to 1800 then climbing right turn to 3100 on heading 230° and on GDM VOR/DME R-167 to LAWNRN/GDM 23 DME and hold, continue climb-in-hold to 3100.

MSA GDM 25 NM
150° 4400 240°
3300

GARDNER
116.95 GDM
Chan 116(Y)

Procedure NA for arrival
on GDM VOR/DME airway
radials 179 CW 246.

TROY INT
PUT 7.8

117.4 PUT
R-030
Chan 121

115.6 PVD
Chan 103

Procedure NA for arrivals
at SPENO on V270
westbound.

HOLD 6000 2800
289° 1 min
109°

(IF/IAF)
SPENO
I-RSR 11.7

2800
109° (6.2)

(IAF)
RILOC INT
I-RSR 5.5

LOCALIZER 110.9
I-RSR
Chan 46

LAWREN
GDM 23

ELEV 1009	D	TDZE 980
-----------	---	----------

WORCESTER RGNL (ORH)
ILS RWY 11 (CAT II & III)