

ILS or LOC RWY 2
COLUMBIA RGNL (COU)

MISSED APPROACH: Climb to 2700 on COU VOR/DME R-020 to BOVEN/COU 6.3 DME and hold, continue climb-in-hold to 2700.



MSA COU 25 NM
3100

HALLSVILLE
114.2 HLV
Chan 89

1616 A

2700 to YATGU
189°
(24.8)
R-020
200°
200°
BOVEN
COU 6.3

COLUMBIA
110.2 COU
Chan 39

967

LOCALIZER
110.7
I-COU
Chan 44

1444 A

NEUKS
I-COU
3.4

2700 to YATGU
202° (6.3)

953 ±

(IAF)
YATGU
I-COU 7.2

201°
min
021°

HOLD
6000
2700

2700
021° (5.9)

(IF)
CATIL
I-COU 13.1

2037 A

3000 NoPT to CATIL
101° hdg (7.3) and
021° (3.9)

COU
Lr-209

(IAF) A
MIZZU
HLV 36.1

201°

ELEV 889 D TDZE 889

HIRL Rwy 2-20
MIRL Rwy 13-31
REIL Rwy 20

ELEV 889

TDZE 889

HIRL Rwy 2-20

MIRL Rwy 13-31

REIL Rwy 20

REIL Rwy 13 and 31

3300 X 100

20

949 ☆

2401 X 150

TWR 960

A5

2

021°