


ILS RWY 28L (CAT II & III)
CHICAGO O'HARE INTL (ORD)

MISSED APPROACH:
Climb to 1200 then
climbing left turn to
4000 direct CGT
VORTAC and hold.



CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED