

VUDOO TWO ARRIVAL (RNAV) Transition Routes

POTOMAC APP CON
126.4 282.375
D-ATIS
133.675 251.05
TOWER
118.4 349.0

R-6611A & B

R-6613A

See following page
for arrival routes

VUDOO
9000

9000
*1500
045°
(10)

9000
*1500
078°
(16)

10 NM

190°
(230K)

13000
*1400
010°
(26)

NOTE: RADAR required.
NOTE: RNAV 1.
NOTE: DME/DME/IRU or GPS required.
NOTE: P56 area A/B 1.5 NM north of DCA,
avoid surface to 18000 MSL.

10 NM

211°
(10)

6 NM

218°
(1210K)

BEEVR
12000

9000
*1500
038°
(16)

GOLOE
13000

11000
*2000
031°
(10)

HANKC

13000
*2000
022°
(16)

THHMP

(CONTINUED ON FOLLOWING PAGE)

BEEVR TRANSITION (BEEVR.VUDOO2): (ATC assigned only).
CIBAC TRANSITION (CIBAC.VUDOO2)
THHMP TRANSITION (THHMP.VUDOO2)

NOTE: Chart not to scale.

VUDOO TWO ARRIVAL (RNAV) Transition Routes

AL-561

VUDOO TWO ARRIVAL (RNAV) Arrival Routes

JOINT BASE ANDREWS (KADW)
CAMP SPRINGS, MARYLAND

POTOMAC APP CON
126.4 282.375
D-ATIS
133.675 251.05
TOWER
118.4 349.0

REVOE
Landing south: Rwy 19L/R:
Expect RADAR vectors to
final approach course after REVOE.

NOTE: RADAR required.
NOTE: RNAV 1.
NOTE: DME/DME/IRU or GPS required.
NOTE: P56 area A/B 1.5 NM north of DCA,
avoid surface to 18000 MSL.

FUNNY
Landing north: Rwy 1L/R:
Expect RADAR vectors to
final approach course after FUNNY.
8000

R-6612

R-6611A & B-

R-6613A

NOTE: Chart not to scale.

ARRIVAL ROUTE DESCRIPTION

LANDING NORTH RWYS 1L/R: From VUDOO on track 348° to cross FUNNY at 8000, then on track 348°. Expect RADAR vectors to final approach course.

LANDING SOUTH RWYS 19L/R: From VUDOO on track 020° to cross BEDLE at 8000, then on track 006° to cross HOLIO at 5000, then on track 006° to DECON, then on track 343° to REVOE, then on track 343°. Expect RADAR vectors to final approach course.

VUDOO TWO ARRIVAL (RNAV) Arrival Routes

(VUDOO.VUDOO2) 10DEC15

CAMP SPRINGS, MARYLAND
JOINT BASE ANDREWS (KADW)

NE-3, 25 DEC 2025 to 22 JAN 2026