

(JAKIE.JAKIE6) 24137

AL-655 (FAA)

CINCINNATI/NORTHERN KENTUCKY INTL (CVG)

# JAKIE SIX ARRIVAL (RNAV) Transition Routes

COVINGTON, KENTUCKY

CINCINNATI APP CON  
119.7 254.25  
D-ATIS  
134.375

RNAV 1 - DME/DME/IRU or GPS.  
RADAR required.

See following  
page for  
arrival routes.

ARTUR TRANSITION (ARTUR.JAKIE6):  
CUBIM TRANSITION (CUBIM.JAKIE6):  
DOLLI TRANSITION (DOLLI.JAKIE6):  
VOLUNTEER TRANSITION (VXV.JAKIE6):

NOTE: Chart not to scale.

(CONTINUED ON FOLLOWING PAGE)

## JAKIE SIX ARRIVAL (RNAV) Transition Routes


(JAKIE.JAKIE6) 21MAR24

**CINCINNATI/NORTHERN KENTUCKY INT'L (CVG)**

**COVINGTON KENTUCKY**

## JAKIE SIX ARRIVAL (RNAV) Arrival Routes

COVINGTON, KENTUCKY



## ARRIVAL ROUTE DESCRIPTION

From JAKIE on track 336° to cross NAVPE at or above 10000, then on track 336° to cross OPAVE between 8000 and 12000.

LANDING RUNWAY 9: From OPAVE on track 334° to cross REENY at or above 8000 and at 210K, then on track 334° to AAJAY, then on track 294° to MAPUC, then on track 276° to cross FLOTT at 6000 and at 210K, then on track 276°. Expect RADAR vectors to final approach course.

LANDING RUNWAYS 18C/R: From OPAVE on track 316° to cross FIDEK at or above 8000 and at 210K, then on track 004° to UBEDE, then on track 006° to cross LEWIN at 6000 and at 210K, then on track 006°. Expect RADAR vectors to final approach course.

LANDING RUNWAY 18L: From OPAVE on track 334° to cross REENY at or above 8000 and at 210K, then on track 334° to AAJAY, then on track 010° to IGOCO, then on track 006° to cross NXHAL at 6000 and at 210K, then on track 006°. Expect RADAR vectors to final approach course.

LANDING RUNWAY 27: From OPAVE on track 358° to cross PIVBE at 7000, then on track 358°.

Expect RADAR vectors to final approach course.

LANDING RUNWAYS 36C/R: From OPAVE on track 276° to cross SPOOD at 8000, then on track 280°. Expect RADAR vectors to final approach course.

## JAKIE SIX ARRIVAL (RNAV) Arrival Routes

COVINGTON, KENTUCKY