

LOC/DME I-BQC 108.9 Chan 26		APP CRS 003°	Rwy Ldg TDZE 727 Apt Elev 748	ILS RWY 36R (CAT II & III) CHARLOTTE/DOUGLAS INTL (CLT)	
				MISSED APPROACH: Climb to 1320 then climbing right turn to 4000 on CLT VOR/DME R-093 to LOCAS INT/24.9 DME and hold.	
D-ATIS 121.15		CHARLOTTE APP CON 128.325 (001°-119°) 257.2 (180°-359°) 120.05 (120°-295°) 307.8 (360°-179°) 134.75 (296°-360°)		CHARLOTTE TOWER 118.1 257.8 (Rwys 18L-36R) 126.4 257.8 (Rwy 18C-36C) 133.35 257.8 (Rwy 18R-36L)	GND CON 121.8 348.6 (W) 121.9 348.6 (E)




Diagram of the ILS RWY 36R approach. The diagram shows the 183° heading, the 180° heading, and the 181° heading. It also shows the 180° heading, the 181° heading, and the 182° heading. The diagram includes the following information:

- 183° heading: 183° heading,