

25331

ILS RWY 28L (SA CAT I & II)
JOHN GLENN COLUMBUS INTL (CMH)

MALSR

A5

MISSED APPROACH: Climb to 1400 then climbing left turn to 3000 direct BU LOM and hold.

Diagram illustrating the TWR (Tower) area, showing two runways:

- TDZL/RCLS Rwy 10R-28L**: Length 8000 X 150. Runway numbers 10L and 28R are indicated. Navigation aids include A5, 28R, and 10L.
- HIRL Rwy 10R-28L and 10L-28R**: Length 10114 X 150. Runway numbers 10R and 28L are indicated. Navigation aids include A5, 28L, and 10R.

VGSI and ILS glidepath not coincident
(VGSI Angle 3.00/TCH 68).

CATEGORY	A	B	C	D
S-ILS 28L		SA CAT I RA 157/14	150 DA 965	
S-ILS 28L		SA CAT II RA 100/12	100 DA 915	

SA CATEGORY I & II ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED

JOHN GLENN COLUMBUS INTL (CMH)
40°00'N-82°54'W **ILS RWY 28L** (SA CAT I & II)