

HI-TACAN Z RWY 26

TACAN GSB Chan 112	APCH CRS 261°	Rwy Idg 11,760 TDZE 109 Arpt Elev 109
------------------------------	-------------------------	--

[USAF]


SEYMOUR JOHNSON AFB (KGSB)

▼ * When ALS inop, increase vis to 1 ¼ miles.
** Circling N of Rwy 8-26 not authorized.



ALSF-1

MISSED APPROACH: Climb to 2200 via GSB R-261 to TULME and hold.



ATIS ★ 317.625	APP CON 123.7 290.9 (258°- 110°) 119.7 273.6 (111°- 257°)	TOWER ★ 126.25 370.875	GND CON 132.45 275.8	CLNC DEL 128.025 270.8
-------------------	---	---------------------------	-------------------------	---------------------------





397



EMERG SAFE ALT 100 NM 3700



CATEGORY	C	D	E
S-26*	540/40	431 (500-34)	
C CIRCLING**	680-1½ 571 (600-1½)	740-2 631 (700-2)	740-2¼ 631 (700-2¼)



|HIRL Rwy 8-26

GOLDSBORO, NORTH CAROLINA

35°20'N-77°58'W

SEYMOUR JOHNSON AFB (KGSB)

Amdt 8 03NOV22

HI-TACAN Z RWY 26