


APP CRS	Rwy Ldg	7614
306°	TDZE	57
	Apt Elev	62

RNAV (RNP) Z RWY 30L


NORMAN Y MINETA SAN JOSE INTL (SJC)


RNP AR APCH.	MALSR	MISSED APPROACH: Climb to 2000 on track 306° to ARTAQ and hold.
For uncompensated Baro-VNAV systems, procedure NA below 1°C or above 54°C. For inop ALS, increase RNP 0.10 all Cats visibility to RVR 5500 and increase RNP 0.30 all Cats visibility to 1½ SM.		

D-ATIS 126.95	NORCAL APP CON 120.1 290.25	SAN JOSE TOWER★ 124.0 (CTAF) 0 257.6	GND CON 121.7	UNICOM 122.95
------------------	--------------------------------	---	------------------	------------------



ELEV	62	D	TDZE	57
------	----	---	------	----



2000	ARTAQ	VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 70).		WOXAR
				1600
See planview for multiple IF locations.				
				
GP 3.00° TCH 54				
CATEGORY	A	B	C	D
RNP 0.10 DA		430/35	373 (400- $\frac{3}{4}$)	
RNP 0.20 DA		464/40	407 (500- $\frac{3}{4}$)	
RNP 0.30 DA		541/50	484 (500-1)	
AUTHORIZATION REQUIRED				