

(JCKE.JCKIE2) 19339

JCKIE TWO ARRIVAL (RNAV) Transition Routes

A-95 (FAA)

ONTARIO INTL (ONT)  
ONTARIO, CALIFORNIA




SOCAL APP CON  
127.0 318.2  
D-ATIS  
124.25  
ONTARIO TOWER  
120.6 360.775

- NOTE: RADAR required.
- NOTE: RNAV 1.
- NOTE: DME/DME/IRU or GPS required.
- NOTE: Turbojet aircraft only.
- NOTE: Expect Rwy 26L unless otherwise assigned by ATC.
- NOTE: Expect local area altimeter setting reaching FL200.
- NOTE: HEYNG transition ATC assigned only.
- NOTE: FEYLA transition Las Vegas area departures only.

NOTE: Chart not to scale.

FEYLA TRANSITION (FEYLA.JCKIE2)  
HEYNG TRANSITION (HEYNG.JCKIE2)  
MARUE TRANSITION (MARUE.JCKIE2)  
NATEE TRANSITION (NATEE.JCKIE2)


(CONTINUED ON FOLLOWING PAGE)



JCKIE TWO ARRIVAL (RNAV) Transition Routes

(JCKE.JCKIE2) 05DEC19

ONTARIO, CALIFORNIA  
ONTARIO INTL (ONT)



ARRIVAL ROUTE DESCRIPTION

From JCKIE on track 222° to cross GBNEY between 14000 and 16000, then on track 229° to cross GRRAY between 12000 and 14000, then on track 217° to cross HINOH between 11000 and 13000.

LANDING RUNWAY 8L/R: From HINOH on track 196° to cross ARRAN at or above 10000 and at or below 250K, then on track 218° to cross FIXUT at 9000, then on track 218° to cross ILONE at 8000, then on track 218° to cross ESAYE at 6000, then on track 211° to cross EFFXX at 6000 and at 210K then on track 267° to CASIE, then on heading 267° or as assigned by ATC. Expect RNAV (RNP) Z RWY 8L approach or RADAR vectors to final approach course.

LANDING RWY 26L/R: From HINOH on track 196° to cross RUMBL at 10000 and at 240K, then on heading 196° or as assigned by ATC. Expect RNAV (RNP) Z RWY 26L approach or RADAR vectors to final approach course.

LOST COMMUNICATIONS

LANDING WEST: Proceed on the RNAV (RNP) Z RWY 26L approach or ILS or LOC RWY 26L approach.

LANDING EAST: Proceed on the RNAV (RNP) Z RWY 8L approach or ILS or LOC RWY 8L approach.