


LOC/DME I-AKN	APP CRS	Rwy Ldg	8501
110.3	301°	TDZE	73
Chan 40		Apt Elev	73

LOC BC RWY 30

KING SALMON (AKN)(PAKN)

DME required.	MISSED APPROACH: Climb to 600 then climbing left turn to 3000 on heading 240° and AKN VORTAC R-210 to OLLER/AKN 15 DME and hold.
When local altimeter setting not received, use WSN/PFWs altimeter setting and increase all MDAs 40 feet.	

ATIS 128.8	ANCHORAGE CENTER 124.8 354.0	KING SALMON TOWER* 118.3 279.5	GND CON 121.9	UNICOM 122.95	CTAF 121.9 352.05
----------------------	--	--	-------------------------	-------------------------	-----------------------------



ELEV 73	D	TDZE 73
MIRL Rwy 18-36 HIRL Rwy 12-30		
KING SALMON, ALASKA Amdt 6A 07AUG25		
KING SALMON (AKN)(PAKN) LOC BC RWY 30		