

## ARRIVAL ROUTE DESCRIPTION

From BREE on track 312° to cross BELLS between 15000 and 17000 and at 270K, then on track 312° to cross TACKe between 13000 and 15000 and at 270K, then on track 312° to cross WARDZ between 12000 and 13000 and at 240K, then on track 312° to cross DIETZ at 12000 and at 210K, then on track 356° to WHOOT, then on track 356° to HEDMN, then on track 356°. Expect RADAR vectors to find approach course.

CRIED TRANSITION (CRIED.BERE3)

OUTLN TRANSITION (OUTLN.BERE3)


PNUTS TRANSITION (PNUTS.BFEE3)

POPSY TRANSITION (POPSY.BEREE3)

POWND TRANSITION (POWND.BEREE3)

STUFT TRANSITION (STUFT.BEREE3)

YUYUN TRANSITION (YUYUN.BEREE3)



NOTE: Chart not to scale.

RNAV 1 - DME/DME/IRU or GPS.  
RADAR required.

BEREE THREE ARRIVAL (RNAV)

(BEREE.BEREE3) 11JUL24

DALLAS-FORT WORTH, TEXAS

DALLAS-FORT WORTH INTL (DFW)