



RNAV (GPS) RWY 21
BRANSON WEST MUNI/EMERSON FLD (FWB)


MISSED APPROACH.
Climb to 3400 direct
EDJON and hold.

UNICOM
123.0 (CTAF) **L**

NoPT for arrival at ENDRS
on V71 southbound.



TDZE 1348

REIL Rwys 3 and 21 **L**

3400	EDJON
	

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 44).

* LNAV only

*LNAV only	HVGA 2.2 NM to RW21
------------	---------------------------

RW21

208

BRNTT

ENDRS

Holding Pattern

9

$$\begin{array}{r} 034^{\circ} \rightarrow \\ \hline 21.4^{\circ} \end{array} \quad 3000$$

214

GP 3.00°
TCH 40

CATEGORY	A	B	C	D
LPV DA	1598-1	250 (300-1)	NA	
LNAV/VNAV DA	1832-1 ⁵ / ₈	485 (500-1 ⁵ / ₈)	NA	
LNAV MDA	1800-1	452 (500-1)	NA	
CIRCLING	1900-1	552 (600-1)	NA	