

WAAS CH 97408 W23A	APP CRS 225°	Rwy Idg 5502 TDZE 18 Apt Elev 18
--	------------------------	---

RNAV (GPS) RWY 23
CURRITUCK COUNTY RGNL (ONX)

RNP APCH.

T For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -15°C (5°F) or above 49°C (120°F). Rwy 23 helicopter visibility reduction below $\frac{3}{4}$ SM NA.

MISSED APPROACH: Climb to 2000
direct EDORY and right turn on track
301° to SUNNS and hold.

AWOS-3 119.775	OCEANA APP CON 123.9 266.8	CTAF 122.9 0
-------------------	-------------------------------	-----------------




Diagram illustrating the RW23 approach procedure. The approach is categorized into A, B, C, and D. The diagram shows the 4 NM Holding Pattern and the 4 NM Holding Pattern.

CATEGORY	A	B	C	D
LPV DA	384-1¼	366 (400-1¼)		
LNNAV/VNAV DA	424-1½	406 (500-1½)		
LNNAV MDA	400-1	382 (400-1)	400-1¼	382 (400-1¼)
CIRCLING	440-1 422 (500-1)	480-1 462 (500-1)	480-1½ 462 (500-1½)	760-2½ 742 (800-2½)