



WAAS CH 51874 W07A	APP CRS 101°	Rwy Ldg 4000 TDZE 140 Apt Elev 143
--	------------------------	---

RNAV (GPS) Z RWY 7
MERRILL FLD (MRI) (PAMR)

RNP APCH - GPS.		MISSED APPROACH: Climbing left turn to 2000 direct BGG VORTAC and hold.
RADAR required for procedure entry.		
T A When local altimeter setting not received, use Ted Stevens Anchorage Intl altimeter setting and increase all MDAs 20 feet. Circling Rwy 16, 34, 5 and 23 NA at night. Helicopter visibility reduction below 1 SM NA.		

ATIS 124.25	ANCHORAGE APP CON 119.1 363.2	MERRILL TOWER ★ 126.0 (CTAF) 0	GND CON 121.7	UNICOM 122.95
-----------------------	---	--	-------------------------	-------------------------



ELEV 143	TDZE 140
REIL Rwys 7, 16, 25, and 34 0 MIRL Rwys 7-25 and 16-34 0	