

WAAS CH 48999 W28A	APP CRS 281°	Rwy Ldg TDZE Apt Elev	10114 815 815
--	------------------------	-----------------------------	--

RNAV (GPS) Y RWY 28L

JOHN GLENN COLUMBUS INTL (CMH)

RNP APCH.

T Simultaneous approach authorized. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -19°C or above 54°C. LNAV procedure NA during simultaneous operations. Use of FD or AP provided RNP track guidance required during simultaneous operations. For inop ALS, increase LNAV Cat C/D visibility to 1 $\frac{3}{8}$ SM.




MALSR




MISSED APPROACH: Climb to 1400 then climbing left turn to 3000 direct BOUTN LOM and hold.

D-ATIS 124.6	COLUMBUS APP CON 125.95 371.975	COLUMBUS TOWER 132.7 257.8	GND CON 121.9 348.6
-----------------	------------------------------------	-------------------------------	------------------------

MISSED APCH FIX



ELEV 815	D	TDZE 815
----------	----------	----------



TDZL/RCLS Rwy 10R-28L
HIRL Rwy 10R-28L and 10L-28R

COLUMBUS, OHIO
Amdt 4 22APR21

40°00'N-82°54'W

JOHN GLENN COLUMBUS INTL (CMH)

RNAV (GPS) Y RWY 28L

EC-2, 09 JUL 2026 to 06 AUG 2026