



LOC/DME I-VUQ 111.9 Chan 56	APP CRS 241°	Rwy Ldg 10900 TDZE 997 Apt Elev 1009
---	------------------------	---

ILS or LOC RWY 24R
JAMES M COX DAYTON INTL (DAY)

ADF required for alternate missed approach.	MALSR 	MISSED APPROACH: Climb to 3000 then right turn direct DQN VOR/DME and hold.
Simultaneous approach authorized. For inop ALS, increase S-LOC 24R Cat A/B visibility to 1 SM; increase Cat C/D visibility to 1½ SM.		

ATIS 125.8	COLUMBUS APP CON 118.85 305.2 (091°-180°) 134.45 323.15 (181°-090°)	DAYTON TOWER 119.9 257.7	GND CON 121.9
----------------------	---	------------------------------------	-------------------------



ELEV 1009		D		TDZE 997	
3000		DQN		HABNU INT I-VUQ 6.8	
I-VUQ 3.4		I-VUQ 2		2600	
1.5 NM		3.4 NM		2600	
CATEGORY		A		B	
S-ILS 24R		1203/24		206 (200-½)	
S-LOC 24R		1520/24		523 (600-½)	
CIRCLING		1580-1		571 (600-1)	
		1580-1½		571 (600-½)	
		1640-2		631 (700-2)	

EC-2, 09 JUL 2026 to 06 AUG 2026

EC-2, 09 JUL 2026 to 06 AUG 2026