


ILS or LOC RWY 3R
DETROIT METRO WAYNE COUNTY (DTW)

MISSED APPROACH: Climb to 1100 then climbing right turn to 4000 on DXO VOR/DME R-122 to GAAGE/DXO 16.1 DME and hold.



GND CON
3 (NW) **119.45** (NE)
5 (SW) **119.25** (SE)



HIRL all Rws
REIL Rws 3L, 9L, 9R and 21R
TDZL/RCLS Rws 3R, 4L, 4R and 22R

