

KUSSO THREE DEPARTURE (RNAV)
(KUSSO3.KUSSO) 14MAY26




WEATHERFORD, TEXAS
PARKER COUNTY (WEA)

LONE STAR DEP CON
135.975 379.9
CTAF
122.7

RNAV 1 - DME/DME/IRU or GPS required.
RADAR required.

**TOP ALTITUDE:
ASSIGNED BY ATC**

TAKEOFF MINIMUMS
Rwys 17, 35: Standard.



NOTE: BDDAY Transition: ATC assigned only.
NOTE: MRSSH Transition: For aircraft inbound to Shreveport, Jackson and Monroe terminal area airports only.

(CONTINUED ON FOLLOWING PAGE)

NOTE: Chart not to scale.

(KUSSO3.KUSSO) 26134
KUSSO THREE DEPARTURE (RNAV)

AL-6497 (FAA)

PARKER COUNTY (WEA)
WEATHERFORD, TEXAS

T

DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 35: Climb on heading 001° to 1600 before turning left.

When entering controlled airspace, fly heading assigned by ATC, expect RADAR vectors to SALVE, then on track 090° to KUSSO, then on assigned transition. Maintain ATC assigned altitude, expect filed altitude 10 minutes after departure.

- BDDAY TRANSITION (KUSSO3.BDDAY)
BSKAT TRANSITION (KUSSO3.BSKAT)
FORCK TRANSITION (KUSSO3.FORCK)
LOOSE TRANSITION (KUSSO3.LOOSE)
MRSSH TRANSITION (KUSSO3.MRSSH)
ZALEA TRANSITION (KUSSO3.ZALEA)

SC-2, 09 JUL 2026 to 06 AUG 2026

SC-2, 09 JUL 2026 to 06 AUG 2026