

TACAN IAG Chan 47 (111.0)	APP CRS 286°	Rwy Ldg TDZE Apt Elev 9129 588 592
---	------------------------	--

TACAN RWY 28

NIAGARA FALLS INTL (IAG)

⚠

Rwy 28 helicopter visibility reduction below RVR 4000 NA.
Circling NA for Cat E southeast of Rwy 6-24.
For inop ALS, increase visibility Cats A/B to RVR 5500,
Cats C/D/E to 1½ SM.

MALSR

MISSED APPROACH: Climbing right turn to 3000 on heading 100° and IAG TACAN R-084 to EDUSE/IAG 15.3 DME and hold, continue climb-in-hold to 3000.

ATIS 120.8 269.4	BUFFALO APP CON 126.5 317.6	NIAGARA TOWER ★ 118.5 (CTAF) 0 349.0	GND CON 125.3 275.8	UNICOM 122.95
----------------------------	---------------------------------------	--	-------------------------------	-------------------------

ELEV 592

D

TDZE 588

286°

9826 X 1.50

5188 X 1.50

TWR

3000	hdg 100°	IAG R-084	EDUSE IAG 15.3
------	----------	-----------	----------------

Emergency Safe Altitude 30 NM 5300

VGSI and descent angles not coincident (VGSI Angle 2.50/TCH 67°).

KESVE IAG 15.3

2200

286°

2000

WEDOD IAG 5.8

2.81° TCH 55

GUMDE IAG 1.7

IAG TACAN

IAG 2.9

0.5 NM	1.1 NM	3 NM	9.5 NM		
CATEGORY	A	B	C	D	E
S-28	1080/40	492 (500-¾)	1080/50	492 (500-1)	
CIRCLING	1100-1	508 (600-1)	1280-2 688 (700-2)	1280-2¼ 688 (700-2¼)	1280-2½ 688 (700-2½)

NIAGARA FALLS, NEW YORK
Orig-A 19MAR26

43°07'N-78°57'W

NIAGARA FALLS INTL (IAG)
TACAN RWY 28