

LOC/DME I-MHR 111.35 Chan 50(Y)	APP CRS 221°	Rwy Ldg 11301 TDZE 98 Apt Elev 98	ILS Y or LOC Y RWY 22L SACRAMENTO MATHER (MHR)	
---	------------------------	--	---	--

TACAN required for procedure entry at BAB TACAN. For non-TACAN equipped aircraft: DME required; RADAR required for procedure entry.			MALSR 	MISSED APPROACH: Climb to 1000, then climbing left turn to 3500 on heading 090° and SAC VORTAC R-058 to COSKA INT/SAC 24.2 DME and hold, continue climb-in-hold to 3500.
⚠️ Circling NA northwest of Rwy 4R-22L. For inop ALS, increase S-ILS Cat E visibility to RVR 4000 and S-LOC Cat C/D/E visibility to RVR 6000. *RVR 1800 authorized with use of FD or AP or HUD to DA.				

ATIS 118.325	NORCAL APP CON 127.4 317.5	MATHER TOWER ★ 120.65(CTAF) 282.25	GND CON 121.85 307.9	UNICOM 122.95
------------------------	--------------------------------------	--	--------------------------------	-------------------------

