

|         |          |      |
|---------|----------|------|
| APP CRS | Rwy Ldg  | 8394 |
| 276°    | TDZE     | 7    |
|         | Apt Elev | 65   |

RNAV (RNP) Z RWY 28R

FORT LAUDERDALE/HOLLYWOOD INTL (FLL)

RNP AR APCH - GPS. RADAR required.

Simultaneous approach authorized. For uncompensated Baro-VNAV systems, procedure NA below 7°C or above 54°C. For inop ALS, increase RNP 0.15 visibility to RVR 5500 and increase RNP 0.30 visibility to 1¾ SM.

MALSR

MISSED APPROACH: Climb to 800 then climbing right turn to 4000 direct HUKUK and hold, continue climb-in-hold to 4000.

|                 |                                |                                      |                  |
|-----------------|--------------------------------|--------------------------------------|------------------|
| D-ATIS<br>135.0 | MIAMI APP CON<br>133.775 285.6 | FORT LAUDERDALE TOWER<br>119.3 257.8 | GND CON<br>121.4 |
|-----------------|--------------------------------|--------------------------------------|------------------|

MISSED APCH FIX  
4 NM  
307°  
127°  
HUKUK

Chart details: HUKUK (IF) 4000 210K, CUSRA, PRHIB (FAF) SNAPE, FUZZY (IF) 4000 276° (6.3), RWY 28R 276° (6.1). Missed approach: HUKUK (IF) 4000 210K, CUSRA, PRHIB (FAF) SNAPE, FUZZY (IF) 4000 276° (6.3), RWY 28R 276° (6.1).

ELEV 65 TDZE 7

800 4000 HUKUK

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 69).

See planview for multiple IF locations.

RWY 28R

SNAPE 2000

GP 3.00° TCH 49

HIRL Rwy 10L-28R and 10R-28L

| CATEGORY    | A | B      | C            | D |
|-------------|---|--------|--------------|---|
| RNP 0.15 DA |   | 362/40 | 355 (300-¾)  |   |
| RNP 0.30 DA |   | 618-1⅓ | 611 (600-1⅓) |   |

AUTHORIZATION REQUIRED

FORT LAUDERDALE, FLORIDA  
Amdt 2 12AUG21

FORT LAUDERDALE/HOLLYWOOD INTL (FLL)  
26°04'N-80°09'W

RNAV (RNP) Z RWY 28R