



ILS or LOC RWY 33
RICHMOND EXEC/CHESTERFIELD COUNTY (FCL)

MISSED APPROACH: Climb to 800, then climbing left turn to 2000 on heading 148° and on RIC VORTAC R-223 to MATOX INT/RIC 16.3 DME and hold, continue climb-in-hold to 2000.

UNICOM
123.05 (CTAF) **L**

800 ↑ 2000 hdg 148° RIC R-223 MATOX △ PUBBS INT I-CFU 6.5 RADAR One Minute Holding Pattern				
*LOC only. I-CFU 1.1 I-CFU 2.4 331° 151° 2000 2000 GS 3.00° TCH 49				
1.3 NM 4.1 NM				
CATEGORY	A	B	C	D
S-ILS 33	417-½ 200 (200-½)			
S-LOC 33	660-½ 443 (500-½)		660-¾ 443 (500-¾)	
CIRCLING	720-1 484 (500-1)	820-1 584 (600-1)	820-1½ 584 (600-1½)	1020-2½ 784 (800-2½)