

PORT ARANSAS**MUSTANG BEACH** (RAS)(KRAS) 2 SW UTC-6(-5DT) N27°48.71' W97°05.33'

5 B NOTAM FILE RAS

RWY 12-30: H3482X70 (ASPH) MIRL**RWY 12:** PAPI(P2L)—GA 3.0° TCH 20'.**RWY 30:** PAPI(P2L)—GA 3.2° TCH 22'. Tree.**SERVICE:** FUEL 100LL**AIRPORT REMARKS:** Attended irregularly. Self serve 24 hrs with credit card. Parachute Jumping. Pedestrians walking on rwy. Rwy 12 has a -3' drop off near end of rwy, Rwy 30 has a 3' ditch 180' from end of rwy. Rwy 30 29' power line 1133' from thld left and right of centerline. 48' power line 1791' from thld left and right of centerline. Overnight tiedown fee.**AIRPORT MANAGER:** 361-749-4008**WEATHER DATA SOURCES:** AWOS-3 118.425 (361) 749-0537.**COMMUNICATIONS:** CTAF 122.9Ⓡ **CORPUS APP/DEP CON** 125.4**CLEARANCE DELIVERY PHONE:** For CD ctc Corpus Christi Apch at 361-299-4230.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CRP**CORPUS CHRISTI (H) VORTACW** 115.5 CRP Chan 102 N27°54.23' W97°26.69' 097° 19.7 NM to fld. 60/9E.

TACAN AZIMUTH & DME unusable:

024°-036° byd 35 NM blo 1,700'

037°-023° byd 35 NM blo 2,000'

265°-275°

VOR portion unusable:

Byd 30 NM blo 1,500'

TACAN AZIMUTH unusable:

080°-085° byd 30 NM

BROWNSVILLE
L-20I, 21A, GOMW
IAP**PORT ISABEL-CAMERON CO** (PIL)(KPIL) 10 NW UTC-6(-5DT) N26°09.97' W97°20.75'

19 B NOTAM FILE PIL

RWY 13-31: H8001X200 (ASPH-CONC) S-105, D-135, 2D-230 MIRL**RWY 13:** REIL. PAPI(P2L)—GA 2.0° TCH 27'.**RWY 31:** REIL. PAPI(P2L)—GA 3.0° TCH 41'.**RWY 08-26:** H5317X150 (CONC) S-50, D-60, 2D-110**RWY 08:** Fence.**RWY 26:** Trees.**RWY 03-21:** H5000X150 (ASPH-CONC) S-30, D-45, 2D-90**RWY 03:** Brush.**RWY 21:** Brush.**RWY 17-35:** H4200X75 (ASPH-CONC) S-30, D-45, 2D-90**RWY 35:** Tower.**SERVICE:** S2 FUEL 100LL, JET A **OX2** LGT Rwy 13 REIL OTS. Rwy 31 REIL OTS.**AIRPORT REMARKS:** Attended 1400-2300Z±. Fuel: self serve with credit card. Parachute Jumping. Rwy 03-21 pavement has hvy grass encroachment. Rwy 08-26 has rough pavement with hvy grass encroachment. No position holding markings on numerous twys apchng rwy intersections. Loose gravel/pavement at intersection of Rwy 13 and northeast twy connecting Rwy 13 and Rwy 21. Rwy 03-21 and Rwy 08-26 markings faded.**AIRPORT MANAGER:** (956) 761-3700**WEATHER DATA SOURCES:** ASOS 118.525 (956) 233-1954.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **VALLEY APP/DEP CON** 119.5

CLNC DEL 119.2

CLEARANCE DELIVERY PHONE: For CD ctc Corpus Christi Apch at 361-299-4230.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BRO.**BROWNSVILLE (H) VORTACW** 116.3 BRO Chan 110 N25°55.44' W97°22.52' 357° 14.6 NM to fld. 10/9E.

TACAN AZIMUTH unusable:

330°-350° byd 32 NM blo 3,000'

350°-010° byd 9 NM

VOR unusable:

330°-350° byd 32 NM blo 3,000'

TACAN DME unusable:

330°-350° byd 32 NM blo 3,000'

350°-010° byd 9 NM

BROWNSVILLE
H-7C, L-20H, 21A
IAP