

CHICAGO/LAKE IN THE HILLS**LAKE IN THE HILLS** (3CK) 38 NW UTC-6(-5DT) N42°12.41' W88°19.38'

887 B NOTAM FILE IKK

RWY 08-26: H3801X50 (ASPH) S-12.5, D-38 LIRL**RWY 08:** PAPI(P2L)—GA 3.0° TCH 20'. Thld dspclcd 360'.**RWY 26:** PAPI(P2R)—GA 3.0° TCH 20'. Thld dspclcd 382'.**SERVICE:** S4 **FUEL** 100LL, JET A **OX** 1, 2, 3, 4 **LGT** ACTIVATE LIRL
Rwy 08-26 —CTAF.**AIRPORT REMARKS:** Attended May-Oct Mon-Sun 1400-2300Z‡, Nov-Apr
Mon-Sun 1500-2200Z‡.**AIRPORT MANAGER:** 815-479-7960**COMMUNICATIONS:** CTAF/UNICOM 123.05® **CHICAGO APP/DEP CON** 120.55**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago Apch at 847-289-0926.**RADIO AIDS TO NAVIGATION:** NOTAM FILE IKK.**NORTHBROOK (H) (H) VORW/DME** 113.0 OBK Chan 77

N42°13.28' W87°57.10' 269° 16.6 NM to fld. 708/2W.

DME unusable:

215°-330° byd 35 NM blo 3,000'

COMM/NAV/WEATHER REMARKS: For VFR wx advisory 5 clicks CTAF. Phone
815-444-1729.**CHICAGO
COPTER
L-28H, A
IAP**