

**FRANKFORT CLINTON CO RGNL** (FKR)(KFKR) 3 W UTC-5(-4DT) N40°16.41' W86°33.73'

CHICAGO

861 B NOTAM FILE HUF

H-5E, 10F, L-27D

RWY 09-27: H5000X75 (ASPH) MIRL

IAP

RWY 09: REIL. PAPI(P2L)—GA 3.0° TCH 25'. Crops.

RWY 27: REIL. PAPI(P2L)—GA 3.0° TCH 25'.

RWY 04-22: H2527X70 (ASPH) S-12.5, D-20 MIRL

RWY 04: Crops.

RWY 22: PAPI(P2R)—GA 4.0° TCH 25'. Road.

**SERVICE:** S2 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 09 and Rwy 27; MIRL Rwy Rwy 04-22 and 09-27—CTAF. MIRL Rwy Rwy 04-22 and 09-27 preset low ints, incr intst—CTAF.

**AIRPORT REMARKS:** Attended 1300-2200Z±. Svc after hrs call amgr. Rwy 04-22 420' swy NE end. 20' wide ditch perpendicular to rwy 100' W of cntrln. Parachute Jumping.

**AIRPORT MANAGER:** 765-654-6275

**WEATHER DATA SOURCES:** AWOS-3 124.325 (765) 654-0328.

**COMMUNICATIONS:** CTAF/UNICOM 123.0

Ⓡ GRISSOM APP/DEP CON 123.85 (1230-0400Z± other times ctc)

Ⓡ CHICAGO CENTER APP/DEP CON 123.85

**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago ARTCC at 630-906-8921.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE OKK.

KOKOMO (H) (H) VORTACW 113.5 OKK Chan 82 N40°31.67'


W86°03.48' 242° 27.7 NM to fld. 826/5W.

TACAN AZIMUTH unusable:

176°-234° byd 35 NM blo 2,400'

VOR unusable:

176°-234° byd 35 NM blo 2,400'



**FRANKLIN FLYING FLD** (3FK) 3 S UTC-5(-4DT) N39°25.59' W86°03.50'

ST LOUIS

740 B NOTAM FILE HUF

RWY 03-21: H2400X35 (ASPH) RWY LGTS(NSTD) 0.6% up SW

RWY 03: Thld dsplcd 125'. Tree.

RWY 21: Thld dsplcd 165'. Crops.


**SERVICE:** S4 FUEL 100LL LGT Actvt lgt-amgr.

**AIRPORT REMARKS:** Attended irregularly. Parachute Jumping.

**AIRPORT MANAGER:** (317) 999-7883

**COMMUNICATIONS:** CTAF/UNICOM 122.7

**CLEARANCE DELIVERY PHONE:** For CD ctc Indianapolis Apch at 317-227-5743.



**FREEMAN MUNI** (See SEYMOUR on page 137)