## **NORTH DAKOTA**

WEST FARGO MUNI (D54) 3 NW UTC-6(-5DT) N46°5/ 896 B NOTAM FILE GFK RWY 18-36: H3300X50 (ASPH-AFSC) S-12.5 LIRL RWY 18: Road. Rgt tfc. SERVICE: S4 FUEL 100LL LGT ACTIVATE LIRL Rwy 18-36( AIRPORT REMARKS: Attended Mon-Fri 1400-2300Z‡. Parachute ju 100LL fuel svc avbl with credit card. Cfm winter conds aft ma AIRPORT MANAGER: 701-371-2655 COMMUNICATIONS: CTAF 122.7 CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651 RADIO AIDS TO NAVIGATION: NOTAM FILE FAR. FARGO (WH) (DH) VORW/DME 116.2 FAR Chan 109 N46°4	L-14G TAF. mping on and invof arpt. Deer and birds on and invof arpt. jor storm–call AMGR 701–371–2655. -463-5588.
FESSENDEN-STREIBEL MUNI (D24) 3 NW UTC-6(-5DT) 1619 NOTAM FILE GFK RWY 08-26: 2940X120 (TURF) LIRL RWY 08: Road. RWY 26: Trees. SERVICE: LGT ACTIVATE LIRL Rwy 08-26—CTAF. AIRPORT REMARKS: Unattended. Waterfowl and deer on or invof arpi and stopway areas. Rwy 08 has lgtd 300 <sup>-/-</sup> stopway and Rwy 2 condition prior to use Oct-Apr. AIRPORT MANAGER: 701-653-5069 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651	during migratory season. Dalgt cone markers at rwy thIds, 6 has 550′ lgtd stopway. No snow removal avbl—confirm
FORT YATES STANDING ROCK (Y27) 1 S UTC-6(-5DT) N46°04.01 ' 1633 B NOTAM FILE GFK RWY 14-32: H3700X60 (ASPH) S-11.5 MIRL RWY 14: Fence. RWY 32: Fence. SERVICE: LGT MIRL Rwy 14-32 on dusk-0600Z‡, after 0600Z AIRPORT REMARKS: Unattended. Birds and waterfowl on and invof 701-455-3662; 701-460-7367. AIRPORT MANAGER: (701) 854-8501 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651 RADIO AIDS TO NAVIGATION: NOTAM FILE BIS. BISMARCK (L) (L) VORW/DME 116.5 BIS Chan 112 N46°43	L-14F ‡ ACTIVATE—CTAF. arpt. Cfm snow removal Oct–Apr; call 701–455–3229; -463-5588.
<ul> <li>GACKLE MUNI (9G9) 1 SW UTC-6(-5DT) N46°37.29′ 1904 NOTAM FILE GFK</li> <li>RWY 08-26: 1620X40 (TURF) 0.4% up W</li> <li>RWY 17-35: 1150X40 (TURF) 0.5% up S</li> <li>AIRPORT REMARKS: Unattended. Arpt CLOSED winter due to lack of cannot see acft at opposite end of rwy due to rwy gradient. + surface rolling; grass clumpy and possible animal holes. Be ale fm Rwy 8 and 26 N edge near rwy midpt.</li> <li>AIRPORT MANAGER: 701-485-3241</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651</li> </ul>	snow removal. Birds on and invof arpt. Pilots at end of rwy 5´ hill 60´ R of AER. Rwy 17–35 and Rwy 08–26 turf rt, Rwy 08 first 200´ rise at 5% slope. Ctn lake shore 20´

GARRISON DAM RECREATIONAL AIRPARK (See RIVERDALE on page 346)