

## RICHMOND

RICHMOND EXEC/CHESTERFIELD CO (FCI)(KFCI) 4 SW UTC-5(-4DT) N37°24.39'

WASHINGTON  
H-10H, 12I, L-36H  
IAP

W77°31.49'

236 B TPA—See Remarks LRA NOTAM FILE DCA

RWY 15-33: H5500X100 (ASPH-GRVD) S-60, D-80 HIRL

0.7% up NW

RWY 15: REIL. PAPI(P4L)—GA 3.0° TCH 43'. Trees.

RWY 33: MALS. PAPI(P4L)—GA 3.0° TCH 50'. Brush.

SERVICE: S4 FUEL 100LL, JET A OX3 LGT HIRL Rwy 15-33 preset low instst; incr instst and actvt MALS. Rwy 33 and REIL Rwy 15—CTAF.

NOISE: Noise sensitive area north of arprt. No wind voluntary use of Rwy 15 preferred.

AIRPORT REMARKS: Attended 1200-0300Z±. Fuel aft hrs call 804-271-7793 or 844-435-9732 btn 0300-1200Z±. 400' twr 5 NM north of arprt. Acft on ILS apch to Richmond Intl crossing over arprt. Med-flight: irregular departure pattern. Helicopter parking adj to Twy C. TPA—1236(1000) single engine, 1736(1500) multi-engine. ARFF eqpt and trained personnel avbl at arprt.

AIRPORT MANAGER: 804-768-7722

WEATHER DATA SOURCES: AWOS-3PT 128.625 (804) 271-8426.

COMMUNICATIONS: CTAF/UNICOM 123.05

® POTOMAC APP/DEP CON 126.75 118.2

CLNC DEL 124.6

CLEARANCE DELIVERY PHONE: For CD ctc Potomac Apch at 866-640-4124.

RADIO AIDS TO NAVIGATION: NOTAM FILE DCA.

FLAT ROCK (H) (H) VORTACW 113.3 FAK Chan 80 N37°31.71' W77°49.69' 123° 16.2 NM to fld. 460/6W.

TACAN 338 radial unusable

VOR unusable:

111°-168°

169°-204° blo 5,000'

274°-337° blo 4,000'

274°-337° byd 33 NM

ILS/DME 108.3 I-CFU Chan 20 Rwy 33. Class IA. LOC/DME unmonitored when arprt unatndd.

