
AIRPORT/FACILITY DIRECTORY



BAK-14 BAK 12B(B) (1500') RWY 26L

HOOK MB 60 (200 ′) → RWY 26R

SERVICE: S4 FUEL 100, JET A, A1+ 0X 1, 2, 3, 4 LGT Rwy 22L PAPI unusable byd 2 NM. Rwy 26L PAPI aligned 05° left of rwy centerline, Rwy 26L PAPI unusable byd 05° right of rwy centerline. Rwy 26R PAPI unusable byd 1.5 NM from thld. MILITARY ---FUEL A++ (Mil; avbl H24) A-GEAR Hook MB100(B) lctd 200' from thld Rwy 26R. Rwy 04R-22L and Rwy 08R-26L sfc grvd within 10' of A-G system. Potential for fighter acft tail hook skip exists. TRAN ALERT 15 WG can provide eqpt but crews must provide own pers when needed.

CONTINUED ON NEXT PAGE

AIRPORT/FACILITY DIRECTORY CONTINUED FROM PRECEDING PAGE

- AIRPORT REMARKS: Attended continuously. 100 octane fuel avbl thru FBO. Bird strike hazard all runways. ASDE-X in use. Opr transponders with altitude reporting mode and ADS-B (if equipped) enabled on all airport surfaces. Due to location of twr, controllers unable to determine whether acft are on correct final apch to Rwy 04L, Rwy 04R, Rwy 22L and Rwy 22R. Due to non-visibility twr una to dtrm if the flwg areas are clear of obstns and/or tfc: ptns of Twy J btn Twy B and Rwy 08R; ptns of Inter-Island acft prkg ramp. Rwy 08L-26R 200' wide with Igts outside, pvmt striped 150' wide. TPA-Tfc pattern altitude for small acft entering from northwest 800(787). Tfc pattern altitude for small acft entering from south 1000(987). Tfc pattern altitude for large acft entering from south 1500(1487). During periods of repeated precipitation anticipate wet rwy conditions, if current conditions rgr confirmation ctc Honolulu twr on initial ctc. Remain at least 1 mile offshore of Waikiki Diamond Head Koko Head and EWA Beach. Arrival Rwy 08L, fly ILS apch procedure or a close-in base leg remaining over center of Pearl Harbor Channel. Arrival Rwy 26L and Rwy 26R, remain at tfc pattern altitudes as long as possible before beginning descent for ldg. Twy G ADG V and below power in w/PPR. Tower approval required to use Taxiway Kilo from Runway 4R. Apron Taxilane 6 btn Twy C and south ramp clsd except GA/fixed wing loading/unloading only. Apron Taxilane 2 east end 360' clsd. Rwy 04R and Rwy 08R wind cones in nonstandard lctn. All jet acft ctc ramp control prior to engine start at gate or hard stand. PPR from arpt manager for transportation of Class A and B explosives in and out of HNL. LRA: 2 hrs advance notice rgr outside regular business hrs. Ldg fee and storage charges collectable on arrival. NOTE: See Area Notices. NOTE: See General Notices—GENERAL INFORMATION ON FLYING TO HAWAII. NOTE: See Special Notices—Tower Data Link System. NOTE: See Special Notices—HNL Runway Incursion Risk. NOTE: See Special Notices-Arrival Alert.
- MILITARY REMARKS: See FLIP AP/3 Supplementary arpt information, route and area rstd, and Oakland FIR flt haz. All acft inbd to Hickam should address flt plan to PHIKYXYX. All military acft with VIP code 7 or abv ctc 15WG command post or relay thru HF/SSB airway 1 hour out to confirm blocktime. All units planning to stage ops from JBPH-H must contact 15 WG/XP (315) 449-1591 at least 60 days prior to arrival. ANG HI ANG afld ops opr 1500-0300Z Mon-Fri and UTA wkends; clsd Sat, Sun and hol. RSID JBPH-H is PPR to all non-TFWC msn, amc trng msn and KC-135 8 un & 8 en msn call 735th moc at DSN (315) 499-6970 for PPR. All amc PPR will be coord Mon-Fri 1700-0400Z only. All non-amc acft such as foreign, sister svc, tran acft or KC-135 and, QDN, QEN, PEN, KEN, CJZ, DV1, DV7, DC5, and C-130 msn must ctc 15 OSS/OSA (AMOPS) at DSN (315) 449-0046 for PPR. All PPR will be apvd no earlier than 72 hr but no later than 24 hr prior. All tran acft not on an AMC/TWCF msn and home stn acft terminating at JBPH-H, will provide a 3 hr out call (comm 808-448-6900) as well as a 20-30 min out call on 292.5 to the 15 WG/CP (KOA CONTROL). Upon arrival, crews will proceed directly to command post (bldg 2050) and complete an outbound setup sheet to facilitate departure requirements. Mil acft opr during Bird Watch Condition MODERATE (initial tkof or full stop ldg only, no multiple IFR/VFR approaches) and SEVERE (tkof and ldg prohibited w/o 15 OG/CC approval or 154 OG/CC approval for HIANG acft) ctc HIK ramp, PTD, 15 WG command post, 735 AMC command post, 154 WG command post for current conditions. Twr apvl rgrd to use Twy Kilo from Rwy 04R. Twy R Hold-Short apch zone Rwy 04L/R at hold line. Twy P clsd to acft over 12500 lbs. CAUTION No fighter transient support available in accordance with ACC LSET Flash Safety 06-02. Transient fighter units should provide their own maintenance support. Foreign object damage hazard exits on all movement areas east of Twy S. FOD hazard exists on all twys and rwys, but especially on Rwy 04L-22R and twys north of Rwy 08L-26R. Fighter acft exercise extreme caution when taxiing. To minimize foreign object damage potential, all acft should use minimum thrust, especially outboard engines, when taxiing past the F-22 alert facility on Twy T. Hickam ramp taxi instr NOT valid within PHNL Airport Operating Area (AOA) which includes Twys A, B, portions of Twys V (south of Twy A) and T, and all rwys. Aircrews must ctc HNL twr or HNL gnd as drct prior to entering or while within the PHNL AOA. Hickam ramp will instr all acft at the Haz cargo pad adj to Twy B, Twys A1-A4, B1-B4 and PHIK ramp side portions of Twy T and V (North of Twy A). TFC PAT Overhead tfc pat alt 2000' rstd to 154 WG (HIANG) and 15 Wing Ftr/C17 and Sentry Aloha acft CSTMS/AG/IMG All military acft rgr Customs/Agriculture/Immigration inspection must ctc 15 WG command post or if Air Mobility Command ctc Hickam AMCC, no later than 3 hrs prior to arrival with departure location, estimated block time, number of aircrew, Civilian/Military Passengers/Foreign Nationals/and Distinguished Visitor codes. MISC Afld ops DSN 449-0046/0048 Fax DSN 449-7624. Wx opr H24, DSN 449-2251, C808-658-9961. Remote flt wx briefings ctc 17th Wx Sq H24, DSN (315) 449–7950/8333, FAX DSN (315) 449–8336; 2 hr prior notice rqr for timely brief. Official obsn taken by FAA. Cooperative wx watch procedures do not exist between Wx and ATC. No COMSEC material avbl thru Hickam Airfield Ops. Due to sensitivities of citizens, fighter aircraft dep only authorized from Mon-Sat 1700-0700Z, and Sun and holidays 1800-0700Z. All request for waivers will be sent to the 15/OG/CC or 154 OG/CC for HIANG aircraft at least 5 working days in advance. Waivers will be granted on extreme necessity. If short notice mission essential waivers are necessary, ctc 150G/CC by phone thru 15 WG Comd Post (15 WG/CP) or 154 OG/CC for HI ANG aircraft. 15 WG Comd Post will pass approval to Hickam flight svc and Hickam ramp advisory. COMM Bedtime (All Coronet W tankers use 311.0 for tanker-fighter inter-plane on launch day. After duty hr DSN 448-8888 613AOC/AMD, Fit Management.

CONTINUED ON NEXT PAGE

AIRPORT/FACILITY DIRECTORY

CONTINUED FROM PRECEDING PAGE

AIRPORT MANAGER: 808-836-6533 WEATHER DATA SOURCES: ASOS (808) 836-0449 WSP. COMMUNICATIONS: D-ATIS 127.9 251.15 PTD 133.6 (HICKAM) R HONOLULU CONTROL FACILITY APP CON 118.3 (West) TOWER 118.1 123.9 (08R-26L) 257.8 273.575 (08R-26L) GND CON 121.9 ADVISORY RAMP 121.8 (HNL INTL) 133.6 254.4 (HICKAM) CLNC DEL 121.4 R HONOLULU CONTROL FACILITY DEP CON 118.3 (West) 124.8 (East) PDC COMD POST 168.0 292.5 295.5 SHAKA OPS 125.3 349.4 AIRSPACE: CLASS B See VFR Terminal Area Chart CLASS E svc Honolulu Intl arpt. VOR TEST FACILITY (VOT) 111.0 RADIO AIDS TO NAVIGATION: NOTAM FILE HNL. HONOLULU (H) VORTAC 114.8 HNL Chan 95 N21°18.50' W157°55.82' at fld. 5/11F. TACAN AZIMUTH & DME unusable: 055°-085° byd 15 NM blo 7,000' 251°-260° byd 20 NM blo 2,200 261°-280° byd 20 NM blo 3,000 281°-305° byd 20 NM blo 7,500 306°-330° byd 30 NM blo 7,500 331°-340° byd 32 NM blo 5,500 360°-055° byd 15 NM blo 6,000' 360°-085° byd 25 NM blo 8,000 360°-085° byd 30 NM blo 12,000 VOR unusable: 055°-085° byd 15 NM blo 7,000' 100°-115° byd 30 NM blo 4,000 120°-140° byd 35 NM blo 5,000 170°-210° byd 20 NM blo 3,000' 240°-250° byd 30 NM blo 3,000 241°-250° byd 35 NM blo 4,000 251°-260° byd 20 NM blo 2,200 261°-280° byd 20 NM blo 3,000 281°-305° byd 20 NM blo 7,500 306°-330° byd 30 NM blo 7,500 331°-340° byd 32 NM blo 5,500' 351°-359° byd 25 NM blo 7,500 360°-055° byd 15 NM blo 6,000 360°-085° byd 25 NM blo 8,000 360°-085° byd 30 NM blo 12,000 KOKO HEAD (H) VORTACW 113.9 CKH Chan 86 N21°15.91' W157°42.18' 274° 12.6 NM to fld. 640/11E. VOR unusable: 285°-294° byd 27 NM blo 8,000' 295°-000° byd 21 NM blo 5,500' 295°-000° byd 32 NM blo 8,000 TACAN AZM/DME unusable: 285°-294° byd 20.5 NM blo 5,000' 285°-294° byd 27 NM blo 8,000 295°-000° bvd 19 NM blo 5.500 295°-000° byd 26 NM blo 8,000' 295°-000° byd 32 NM HN N21°19.48' W158°02.94' 082° 7.2 NM to fld. 43/11E. EWABE NDB (MHW/LOM) 242 ILS/DME 110.5 I-IUM Chan 42 Rwy 04R. Class IE. ILS/DME 111.7 I-HNL Chan 54 Rwy 08L. Class IE. LOM EWABE NDB. Excessive oscillation over mnts ne of LOM. LDA/DME 109.1 I-EPC Chan 28 Rwy 26L. LOC unusable byd 25 degrees north of centerline due to terrain. ASR COMM/NAV/WEATHER REMARKS: San Francisco Radio, see Associated Data. Excessive needle oscillation can be expected over mountainous terrain NE of NDB-CAUTION advised. Hickam ramp twr (Non-ATC facility) All acft on HIK flightline including haz cargo pad will ctc HIK Ramp prior to eng start/taxi. HIK Ramp will provide advisory directions and will relay to AFLD Ops via VHF capable acft. All acft departing to CONUS must complete USDA inspection prior to eng start/taxi. Rwys 4R and 8R wind cones in nonstandard lctn. WATERWAY 08W-26W: 5090X300 (WATER) WATERWAY 04W-22W: 3000X150 (WATER)

SEAPLANE REMARKS: Rwy 04W-22W and Rwy 08W-26W recreational boating activities on and invof waterways.