

## AMERICUS

**JIMMY CARTER RGNL** (ACJ)(KACJ) 4 NE UTC-5(-4DT) N32°06.65' W84°11.33'

ATLANTA  
H-9A, 12F, L-18J

468 B NOTAM FILE MCN

**RWY 05-23:** H6011X100 (ASPH) S-30, D-50 HIRL

**RWY 05:** PAPI(P2L)—GA 3.0° TCH 58'. Tree.

**RWY 23:** MALSF. REIL. PAPI(P2L)—GA 3.0° TCH 59'.

**RWY 10-28:** H3786X75 (ASPH) S-30

**RWY 10:** Trees.

**RWY 28:** Trees.

**SERVICE:** S4 FUEL 100LL, JET A LGT ACTIVATE HIRL Rwy 05-23,

PAPI Rwy 05 and Rwy 23 and MALSF Rwy 23—CTAF.

**AIRPORT REMARKS:** Attended 1300-0100Z†. Wildlife activity on and in/ovf arpt.

**AIRPORT MANAGER:** 229-924-2813

**WEATHER DATA SOURCES:** AWOS-3 128.375 (229) 928-0934.

**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ ATLANTA APP/DEP CON 124.2 (1115-0400Z‡)

CLNC DEL 119.95

ATLANTA CENTER APP/DEP CON 134.5 (0400-1115Z‡)

CLNC DEL 134.5

**CLEARANCE DELIVERY PHONE:** For CD ctc Atlanta Apch at 678-364-6132, when Apch clsd ctc Atlanta ARTCC at 770-210-7692.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE ABY.


**PECAN (L) (L) VORW/DME** 116.1 PZD Chan 108 N31°39.31' W84°17.59' 013° 27.8 NM to fld. 292/2W.

DME unusable:

220°-360° byd 30 NM blo 3,000'

**LINDBERGH NDB (MHW)** 242 LKG N32°10.47' W84°06.49' 231° 5.6 NM to fld. 469/4W. NOTAM FILE MCN.

**ILS** 110.5 I-ACJ Rwy 23. Class IB.



## ASHBURN

**TURNER CO** (75J) 2 SE UTC-5(-4DT) N31°41.26' W83°37.98'

JACKSONVILLE  
L-18J  
IAP

389 B NOTAM FILE MCN

**RWY 17-35:** H5005X75 (ASPH) S-30 MIRL

**RWY 17:** Trees.

**RWY 35:** Trees.

**SERVICE:** LGT MIRL Rwy 17-35 opr dusk-0500Z†. After 0500Z†, ACTIVATE MIRL Rwy 17-35—CTAF. Rotating bcn lctd on water tank 1/4 mile NW of arpt.

**AIRPORT REMARKS:** Unattended.

**AIRPORT MANAGER:** 229-567-3563

**COMMUNICATIONS:** CTAF/UNICOM 122.7

Ⓡ JACKSONVILLE CENTER APP/DEP CON 125.75

**CLEARANCE DELIVERY PHONE:** For CD ctc Valdosta Apch at 229-257-2207, when Apch clsd ctc Jacksonville ARTCC at 904-845-1592.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE MCN.

**VIENNA (L) (L) VORTAC** 116.5 VNA Chan 112 N32°12.81'

W83°29.84' 191° 32.2 NM to fld. 300/1E.

TACAN DME unusable:

014°-024°

