ALASKA

320 NOTAM FILE ENA WATERWAY N-S: 6000X400 (WATER)	UTC-9(-8DT) N61°36.81	1′W149°39.93′	
SERVICE: S4 NOISE: Seymour Lake may be subject to "annoying noises" between the hours SEAPLANE REMARKS: Unattended. Public and trees in immediate vicinity.	s of 11:00pm and 8:00am.	-	-
AIRPORT MANAGER: 907-841-4069 COMMUNICATIONS: CTAF 122.8 COMM/NAV/WEATHER REMARKS: For a toll fi	ree call to Kenai FSS dial 1–86	6–864–1737.	
SOLOY STRIP (87AK) PVT 10 NE 545 NOTAM FILE Not insp. RWY 07-25: 1100X50 (GRVL) RWY 07: Trees. RWY 25: Trees. Rgt tfc. AIRPORT REMARKS: Attended Mon–Fri 17 AIRPORT MANAGER: (907) 315-5300 COMMUNICATIONS: CTAF 122.8 COMM/NAV/WEATHER REMARKS: For a toll fr	00–0200Z‡.	;/ W149°17.31 / ;6-864-1737.	ANCHORA
330 NOTAM FILE ENA WATERWAY NE-SW: 5500X800 (WATER) SEAPLANE REMARKS: Unattended. Waterw visual inspection prior to use. Transi Haul out facility avbl PPR call 907- avbl call 907–376–2288. No public property on lake perimeter is private. south side of lake. Be alert: winter co drifts and strong NE winds in excess and outlet. Be alert for boaters, wate and floating debris. AIRPORT MANAGER: 907-376-2118 COMMUNICATIONS: CTAF 122.8 RADIO AIDS TO NAVIGATION: NOTAM FILE BIG LAKE (H) (H) VORTACW 112.5 BCC	vay not monitored, recommend ient parking avbl on south shor 376–2118. Long-term slip lez c shore access. All docks and Privately maintained windsock nditions vary, possible heavy sn of 60 mph, avoid thin ice at in er skiers, snow machine activit ENA. GQ Chan 72 N61°34.17′ to fld. 179/19E.	re. ase ion low y y y y y y y y y y y y y y y y y y y	ANCHORAU
VALLEY FLYING CROWN (AK27) PVT 400 NOTAM FILE Not insp. RWY 06–24: 1800X30 (GRVL) RWY 24: Rgt tfc. AIRPORT REMARKS: Unattended. Power li break–up. AIRPORT MANAGER: 907-232-3930 COMMUNICATIONS: CTAF 122.8 COMM/NAV/WEATHER REMARKS: For a toll fi	5 NW UTC-9(-8DT) N	161°38.55′ W149°37.47′ ip not maintained in winter. Rwy s	ANCHORA(
VISNAW LAKE SPB (T66) 7 NW U 300 NOTAM FILE ENA WATERWAY N-S: 4000X200 (WATER) WATERWAY S: Rgt tfc. SEAPLANE REMARKS: Unattended. Tsnt sv of lake. Waterway N-S: more than t AIRPORT MANAGER: 907-947-4052 COMMUNICATIONS: CTAF 122.8 COMMUNICATIONS: CTAF 122.8	UTC-9(-8DT) N61°37.14 ′ c not authorized. Ctn: Hvy tfc a wo TGL not autorizied. Mntn tf	W149°40.71' area; nmrs SPBs & arpts invof. Rec fc pat W of lake. Grvl ramp E shore	ANCHORAC