

HUMBOLDT N48°52.15' W97°07.07' NOTAM FILE PNM.
 (H) TACAN 112.4 HML Chan 71 303° 6.6 NM to Pembina Muni. 797/9E.
 TACAN AZIMUTH unusable:
 075°-085° blo 10,000'
 086°-254° byd 35 NM blo 3,000'
 255°-270°
 271°-074° byd 35 NM blo 3,000'

TWIN CITIES
 H-2H, L-14G

HUSSK N45°28.74' W93°58.12' NOTAM FILE STC.
 NDB (LOMW) 342 ST 314° 5.6 NM to St Cloud Rgnl. 985/3E.

TWIN CITIES

HUTCHINSON MUNI/BUTLER FLD (HCD)(KHCD) 2 S UTC-6(-5DT) N44°51.59' W94°22.95'

TWIN CITIES

1062 B NOTAM FILE HCD

L-12I, 14H

RWY 15-33: H4000X75 (ASPH) MIRL

IAP

RWY 15: REIL. PAPI(P4L)—GA 3.0° TCH 40'.

RWY 33: REIL. PAPI(P4L)—GA 3.0° TCH 40'.

SERVICE: S4 FUEL 100LL, JET A LGT ACTVT or incr intst REIL Rwy 15 and 33; PAPI Rwy 15 and 33; MIRL Rwy 15-33—CTAF. MIRL Rwy 15-33 preset low intst.

AIRPORT REMARKS: Attended Mon-Fri 1400-2300Zt. 100LL avbl H24 via credit card. A avbl H24 via credit card.

AIRPORT MANAGER: 320-234-4473

WEATHER DATA SOURCES: AWOS-3 118.525 (320) 587-3343.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓜ MINNEAPOLIS CENTER APP/DEP CON 127.1

GCO 121.725 (MINNEAPOLIS CENTER and FLIGHT SERVICES)

CLEARANCE DELIVERY PHONE: For CD if una via GCO ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE PNM.

DARWIN (L) (L) VORTACW 109.0 DWN Chan 27 N45°05.25'
 W94°27.23' 160° 14.0 NM to fld. 1130/7E.

