

BEULAH (95D) 2 SW UTC-6(-5DT) N47°15.07' W101°48.90'

1791 B NOTAM FILE GFK

BILLINGS

L-14F

RWY 10-28: H4030X60 (ASPH) S-12.5 LIRL(NSTD)

RWY 10: Tree.

RWY 28: SAVASI(S2L)—GA 3.0° TCH 25'. Road.

SERVICE: S4 **FUEL** 100LL **LGT** ACTIVATE LIRL Rwy 10-28; SAVASI Rwy 28; rotating bcn—CTAF. Rwy 10-28 NSTD LIRL 20' from edge of asph surface.

AIRPORT REMARKS: Attended Oct-Apr Mon-Sat. Amgr on call consly 710-873-4100. For fuel call 701-873-4100/2259/2311. Birds and deer on and invof arpt. Snow removal irregular, confirm winter conditions with arpt manager 701-873-4100 or 701-870-4100. Stacks 600' AGL 6 mile north unlgtd. Lgtd stack 498' AGL located 1.8 NM south. 250' AGL stack with invisible flame to 250' above stack located 8 NM NNW. Arpt located in river valley with 200' ridges surrounding arpt 1500' from thld.

AIRPORT MANAGER: 701-873-4100

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE DIK.

DICKINSON (VH) (H) VORTACW 112.9 DIK Chan 76 N46°51.60' W102°46.41' 045° 45.8 NM to fld. 2527/14E.

VOR unusable:

010°-020° byd 40 NM blo 18,000'

180°-230° byd 40 NM

260°-270°

