

## CONTINUED FROM PRECEDING PAGE

WEATHER DATA SOURCES: ASOS 127.125 (814) 793-9655.

COMMUNICATIONS: CTAF 123.6 UNICOM 123.0

RCO 122.2 (ALTOONA RADIO)

Ⓡ JOHNSTOWN APP/DEP CON 121.2 (1200-0400Z‡)

Ⓡ CLEVELAND CENTER APP/DEP CON 124.4 (0400-1200Z‡)

CLEARANCE DELIVERY PHONE: For CD ctc Johnstown Apch at 814-532-5960, when Apch clsd ctc Cleveland ARTCC at 440-774-0213.

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE AOO.

ST THOMAS (L) TACAN Chan 97 THS (115.0) N39°55.99' W77°57.06' 329° 27.6 NM to fld. 2338/7W.

ILS 111.1 I-AOO Rwy 21. Class IA. LOC unusable byd 25° right of course.

**ARNOLD PALMER RGNL** (See LATROBE on page 288)

**BALLY**

**BUTTER VALLEY GOLF PORT** (7N8) 1 E UTC-5(-4DT) N40°23.85' W75°33.79'

**NEW YORK**

500 NOTAM FILE IPT

**RWY 16-34:** H2420X85 (ASPH-TURF)

**RWY 16:** Thld dsplcd 205'. Road.

**RWY 34:** Thld dsplcd 250'. Road.

**AIRPORT REMARKS:** Attended daylight hours. Rwy 16-34 located in middle of golf course. Trees and substantial terrain elevation changes within 125' of each rwy edge. Rwy 16-34 1535 ft X 24 ft asph insert at S end; remainder turf. Rwy 16 marked with yellow wood panels; turf rwy edges marked with tires painted yellow. Rwy 34 dsplcd thld marked with 3 white lines.

Rwy 16 dsplcd thld marked by 3 yellow tires. Rwy 34: 119 ft tree line 1472 ft fm rwy end; 233 ft right. 12:1 slope to dthr.

**AIRPORT MANAGER:** 610-845-2491

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Allentown Apch at 800-728-6322.

**BANDEL** (See EIGHTY FOUR on page 274)

**BAUBLITZ COMMERCIAL** (See BROGUE on page 266)

**BEAVER CO** (See BEAVER FALLS on page 262)