

**CONNER****WEST FORK LODGE** (4U7) 5 SW UTC-7(-6DT) N45°51.74' W114°13.07'

GREAT FALLS

4249 NOTAM FILE GTF

**RWY 02-20:** 2600X65 (TURF-GRVL) 0.7% up S**RWY 02:** Tree.**RWY 20:** Road.

**AIRPORT REMARKS:** Unattended. Livestock, birds and wildlife invof arpt. No sn plowing in winter. Rwy 02-20 ocnl grvl down cntr of rwy-sml dip 600 ft fm Rwy 20 end. Steep terrain surrounding arpt. Trees and structures in transitional sfc full length both sides of rwy. Rwy 02 +35 ft trees 600 ft fm rwy end and mt 2700 ft fm thr; Rwy 20 +135 ft tree 80 ft R and 120 ft fm rwy end; +115 ft trees bgn 91 ft R penetrating apch sfc.

**AIRPORT MANAGER:** (831) 884-3602**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.**CONRAD** (SØ1) 1 W UTC-7(-6DT) N48°10.10' W111°58.59'

GREAT FALLS

3548 B NOTAM FILE GTF

L-13C

**RWY 06-24:** H4602X75 (ASPH) S-12.5 MIRL 0.4% up SW

IAP

**RWY 06:** P-line.**RWY 24:** REIL. PAPI(P2L)—GA 3.0° TCH 27'.**RWY 15-33:** 2800X100 (TURF) 0.4% up SE**SERVICE:** FUEL 100LL LGT ACTVT REIL Rwy 24; PAPI Rwy 24; MIRL

Rwy 06-24—CTAF.

**AIRPORT REMARKS:** Unattended. 100LL 24/7 self svc. Twys have reflectors.

Rwy 06-24 has uneven sfc, cracks and rprs. Resurfacing sked 2024.

Rwy 06 faded and flaking paint. Rwy 24 faded and flaking paint.

**AIRPORT MANAGER:** (406) 450-1620**COMMUNICATIONS:** CTAF/AUNICOM 122.8**CUT BANK RCO** 122.2 (GREAT FALLS RADIO)® **SALT LAKE CENTER APP/DEP CON** 133.4**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CTB.**CUT BANK (VL) (DH) VOR/DME** 113.35 CTB Chan 80(Y)

N48°33.90' W112°20.60' 131° 28.0 NM to fld. 3791/17E.

VOR unusable:

049°-053° byd 40 NM

061°-073° byd 40 NM

079°-090° byd 40 NM

125°-130° byd 40 NM

143°-149° byd 40 NM

167°-177° byd 40 NM blo 9,000'

167°-177° byd 54 NM

178°-190° byd 40 NM

191°-201° byd 40 NM blo 12,000'

191°-201° byd 53 NM

202°-260° byd 40 NM

271°-282° byd 40 NM

