226 WASHINGTON

```
CLE ELUM
```

CLE ELUM MUNI (\$93) 1 E UTC-8(-7DT) N47°11.65′ W120°53.04′

1945 B NOTAM FILE SEA

RWY 07-25: H2379X60 (ASPH) MIRL 0.3% up W RWY 07: REIL, PAPI(P2L)—GA 4.0° TCH 20′. Ret tfc.

RWY 25: REIL, PAPI(P2L)—GA 4.0° TCH 20'.

SERVICE: LGT PAPI Rwy 07 and Rwy 25 opr continuously. ACTIVATE rotating bcn, MIRL Rwy 07–25 and REIL Rwy 07 and Rwy 25—CTAF.

AIRPORT REMARKS: Unattended. Wildlife on and invof rwy. Gliders use CTAF freq 122.3.

AIRPORT MANAGER: 509-674-2262

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

DE VERE FLD (2W1) 3 E UTC-8(-7DT) N47°10.65′ W120°51.16′

SEATTLE

SEATTLE

1800 NOTAM FILE SEA RWY 08-26: H2055X30 (ASPH)

RWY 08: Trees. Rgt tfc.

RWY 26: Trees.

AIRPORT REMARKS: Attended dalgt hrs. Fld occasionally CLOSED in winter. Wildlife on and invof rwy. Rwy 08–26 has 2 inch dropoff along entr rwy both sides. Rwy 08–26 svr unsealed cracks and joints. Rwy 08–26 NSTD mrkgs no nrs, small and square aiming points painted on rwy ends. All patterns to the south. Rwy 08–26 mrkgs faded.

AIRPORT MANAGER: 509-962-2066 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

COLFAX

LOWER GRANITE STATE (ØØW) 12 S UTC-8(-7DT) N46°40.37′ W117°26.50′

SEATTLE

719 NOTAM FILE SEA

RWY 14–32: 3400X50 (GRVL) 0.9% up SE

RWY 14: Trees.

RWY 32: Hill.

AIRPORT REMARKS: Unattended. Do not land if snow present on rwy. No winter snow removal ops. Pedestrians, vehicles and animals on and invof rwy. Ctc WA State Aviation Division 360–709–8015 or 1–800–552–0666 WA area for facility info prior to use. For acft accidents/incidents ctc WA state emergency operations center 800–258–5990. Ck density altitude. Gravel portions of rwy sfc rough and soft. Rwy marked with reflectors dur dates arpt is open. Steep drop off on both sides of runway.

AIRPORT MANAGER: (360) 618-2477 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

PORT OF WHITMAN BUSINESS AIR CENTER (S94) 3 SW UTC-8(-7DT) N46°51.52′ W117°24.84′ SEATILE 2181 B TPA—3010(829) NOTAM FILE SEA L-138

RWY 08-26: H3209X60 (ASPH) S-17 MIRL 1.0% up E

RWY 08: Thid dsplcd 492´. Road. RWY 26: Thid dsplcd 450´. Hill.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 08: TORA-3209 TODA-3209 ASDA-3209 LDA-2718 **RWY 26**: TORA-3209 TODA-3209 ASDA-3209 LDA-2890

SERVICE: LGT ACTIVATE MIRL Rwy 08–26—CTAF.

AIRPORT REMARKS: Attended May-Sept dawn-dusk, Oct-Apr, Mon-Fri dawn-dusk. Deer invof rwy. Watch for birds invof creek south of arpt. Rwy 08–26 farm machinery may be opr in flds on both sides of rwy and off both rwy ends. 30′ bldg 250′ south AER 26. Dense agricultural ops Feb-Oct.

AIRPORT MANAGER: 509-397-2061

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE PUW.

2772/20E. DME unmonitored.

DME unusable:

040°-045° byd 35 NM blo 8,000 '

065°-070° byd 30 NM blo 7,000° 090°-095° byd 35 NM blo 7,000°

VOR unusable:

032°-100° byd 40 NM 155°-195° byd 40 NM