GREENSBORO EXEC (3A4) 8 SE UTC-5(-4DT) N35°56.52′ W79°41.13′ 739 NOTAM FILE RDU

CHARLOTTE L-25E, 36F

RWY 17-35: H3063X30 (ASPH) S-8 MIRL 2.2% up S

RWY 17: Trees.

RWY 35: Trees.

SERVICE: S4 LGT Actvt MIRL Rwy 17–35, 5 clicks only—CTAF more than 5 lock out control for 10 min. Rwy 17–35 only two end Igts each side.

AIRPORT REMARKS: Attended 1200–22002‡. Parachute Jumping. Rwy 17 uphill Idg preferred. Rwy 17–35 turn–arounds are part of the rwy, there is no runup area at either end. Rwy 17–35 numbers smaller than std. Rwy 17 has 50′ drop off 60′ from rwy end offset 30′ both sides of centerline. Numerous +50′ trees in the apchs and along the sides of the rwy; numerous +15′ trees in the prim sfc.

AIRPORT MANAGER: 336-420-8623

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Greensboro Apch at 743-222-6129.
RADIO AIDS TO NAVIGATION: NOTAM FILE RDU.

LIBERTY (VL) (L) VORTAC 113.0 LIB Chan 77 N35°48.70′ W79°36.76′ 339° 8.6 NM to fld. 828/3W.

