

KASIGLUK (ZØ9)(PFKA) 2 S UTC-9(-8DT) N60°52.40' W162°31.46'

48 B NOTAM FILE ENA

RWY 17-35: 3000X60 (GRVL-DIRT) MIRL 0.7% up S

SERVICE: LGT Actvt MIRL Rwy 17-35—CTAF. Apt bcn sked: ctc AMGR.

AIRPORT REMARKS: Unattended. Birds on and invof arpt. Rwy condition not monitored, recommend visual inspection prior to using. Wind turbines within the tfc pat. Lgts at top of twr, not blades. Rwy 17-35 slopes up to S end 1% grade. Rwy 17 first 200 ft soft when wet.

AIRPORT MANAGER: (907) 543-2498

COMMUNICATIONS: CTAF 122.9


Ⓡ **ANCHORAGE CENTER APP/DEP CON** 125.2

RADIO AIDS TO NAVIGATION: NOTAM FILE BET.

BETHEL (H) (H) VORTACW 114.1 BET Chan 88 N60°47.09'

W161°49.46' 271° 21.2 NM to fld. 105/14E.

BETHEL
L-3C
IAP



KASILOF

ENCELEWSKI LAKE SPB (AK5) 5 S UTC-9(-8DT) N60°15.33' W151°18.18'

230 NOTAM FILE ENA

WATERWAY 09W-27W: 3500X500 (WATER)

SEAPLANE REMARKS: Unattended. Public aces N end of lake. Windssock midlake W side.

AIRPORT MANAGER: 907-398-2201

COMMUNICATIONS: CTAF 122.5

MC GRATH

KASILOF (5KS) 2 N UTC-9(-8DT) N60°21.03' W151°15.77'

125 NOTAM FILE ENA

RWY 01-19: 2400X60 (GRVL)

RWY 01: Trees.

RWY 19: Brush.

AIRPORT REMARKS: Unattended. Maint irreg. Rwy cond nmnt, rcmand visual insp prior to use. ATV tfc on rwy. Rwy 01-19 3 in ruts. Rwy 01 edge not mkd. Windssock blw tree line and may be unrel. Prkg area S end.

AIRPORT MANAGER: 907-953-6733

COMMUNICATIONS: CTAF 122.5

RADIO AIDS TO NAVIGATION: NOTAM FILE ENA.

KENAI (H) (H) VORW/DME 117.6 ENA Chan 123 N60°36.88'

W151°11.71' 168° 16.0 NM to fld. 115/19E.

VOR unusable:

348°-015° byd 20 NM

DME unusable:

355°-041° byd 35 NM blo 2,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial

1-866-864-1737. Kenai FSS—283-7211.

ANCHORAGE

