

**NIKOLSKI AS** (IKO)(PAKO) 0 NE UTC-9(-8DT) N52°56.49' W168°50.94'**DUTCH HARBOR**

77 NOTAM FILE CDB


L-2J

**RWY 08-26:** 3512X135 (GRVL)**RWY 26:** Hill.**AIRPORT REMARKS:** Unattended. Winds in excess of 10 kts from 330-045 deg may produce severe turbulence. Field rolling, acft at one end of rwy cannot see acft at other end. Rwy 08-26 not maintained. Runway may be very soft with ponding during heavy precipitation.**AIRPORT MANAGER:** 907-576-2203**COMMUNICATIONS:** CTAF 122.9Ⓡ **ANCHORAGE CENTER APP/DEP CON** 118.0**COMM/NAV/WEATHER REMARKS:** For a toll free call to Cold Bay FSS dial 1-800-478-7250. For a toll-free call to Kenai FSS dial 1-866-864-1737.**NINILCHIK** (NIN) 3 SE UTC-9(-8DT) N60°01.21' W151°35.37'**MC GRATH**

276 NOTAM FILE HOM

**RWY 10-28:** 2400X60 (GRVL)**RWY 10:** Road.**RWY 28:** Trees.**AIRPORT REMARKS:** Unattended. State maintained on irregular basis. Rwy condition not monitored. Recommend visual inspection prior to use. Ultralight activity invov arpt. Rwy 10 edges not marked. Safety areas at both rwy ends soft.**AIRPORT MANAGER:** 907-262-1187**COMMUNICATIONS:** CTAF 122.9**RADIO AIDS TO NAVIGATION:** NOTAM FILE HOM.**HOMER (H) VOR/DME** 114.6 HOM Chan 93 N59°42.57'

W151°27.40' 333° 19.1 NM to fld. 1626/15E.

**COMM/NAV/WEATHER REMARKS:** For a long distance call to Homer FSS dial 907-235-8588. For a toll free call to Kenai FSS dial 1-866-864-1737.**NIXON FORK MINE** (See MC GRATH on page 166)**NOATAK** (WTK)(PAWN) 1 SW UTC-9(-8DT) N67°33.67' W162°58.83'**NOME**

92 B NOTAM FILE WTK

H-1A, L-4H

**RWY 01-19:** 3992X60 (GRVL) MIRL

IAP

**RWY 01:** PAPI(P4L)—GA 3.0° TCH 30'.**RWY 19:** Brush.**SERVICE:** LGT ACTVT PAPI Rwy 01; MIRL 01-19—CTAF. Rwy 01 PAPI unusbl byd 5 degs left of cntrl.**AIRPORT REMARKS:** Unattended. Rwy condition not monitored, recommend visual inspection prior to landing.**AIRPORT MANAGER:** 907-442-3147**WEATHER DATA SOURCES:** AWOS-3P 135.75 (907) 485-2203. (WX CAM)**COMMUNICATIONS:** CTAF/UNICOM 122.8**NOATAK RCO** 122.4 (KOTZEBUE RADIO)**ANCHORAGE CENTER APP/DEP CON** 119.2 263.0**RADIO AIDS TO NAVIGATION:** NOTAM FILE WTK.**NDB/DME (MHW)** 414 OQK Chan 39 N67°34.21'

W162°58.36' at fld. 85/11E.

**COMM/NAV/WEATHER REMARKS:** For LC to Kotzebue FSS dial 907-442-3310. For a toll free call to Kotzebue FSS dial 1-800-478-7460. For a toll free call to Fairbanks FSS dial 1-866-248-6516.