

FREDONIA (1K7) 2 N UTC-6(-5DT) N37°34.84' W95°50.23'

882 B NOTAM FILE ICT

RWY 17-35: H4557X60 (CONC) LIRL

RWY 17: Pole.

RWY 35: Thld dsplcd 541'.

AIRPORT REMARKS: Unattended. Wildlife on and invof arpt. Rwy 17 nstd NPI mkgs, no thld bar present. Rwy 35 nstd small bsc markings. A drainage ditch 70' left of AER 17 runs parallel 700'.

AIRPORT MANAGER: 620-378-2231

COMMUNICATIONS: CTAF 122.9


CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE CNU.

CHANUTE (L) DME 109.2 CNU Chan 29 N37°37.57' W95°35.61' 257° 11.9 NM to fld. 1085.

KANSAS CITY

L-15E



FREEMAN FLD (See JUNCTION CITY on page 111)

GARDEN CITY RGNL (GCK)(KGCK) 8 SE UTC-6(-5DT) N37°55.65' W100°43.47'

2891 B ARFF Index—See Remarks NOTAM FILE GCK

RWY 17-35: H7299X100 (CONC-GRVD) S-76, D-91, 2S-114, 2D-125 PCN 38 R/C/W/T HIRL

RWY 17: REIL. VASI(V4L)—GA 3.0° TCH 39'.

RWY 35: MALS. VASI(V4L)—GA 3.0° TCH 41'.

RWY 12-30: H5700X100 (CONC) S-48, D-60 PCN 35 R/C/W/T MIRL

RWY 12: REIL. PAPI(P2L)—GA 3.0° TCH 47'.

RWY 30: REIL. PAPI(P2L)—GA 3.0° TCH 46'.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 12: TORA-5700 TODA-5700 ASDA-5700 LDA-5700

RWY 17: TORA-7299 TODA-7299 ASDA-7299 LDA-7299

RWY 30: TORA-5700 TODA-5700 ASDA-5700 LDA-5700

RWY 35: TORA-7299 TODA-7299 ASDA-7299 LDA-7299

SERVICE: S4 FUEL 100LL, JET A OX2 LGT ACTIVATE MIRL Rwy 12-30, HIRL Rwy 17-35, REIL Rwy 17, Rwy 12, Rwy 30 and MALS Rwy 35—CTAF. PAPI Rws 12 and 30 on 24 hrs

AIRPORT REMARKS: Attended 1300-0300Z†. For svc after hrs call 620-275-5055. Class I, ARFF Index A CLOSED to unscheduled air carrier ops with more than 30 passengers seats except PPR 48 hrs call arpt manager 620-276-1190/ 620-290-3810. ARFF Index B provided. Air carrier ops are not authorized in excess of 15 mins before or after scheduled arrival/departure times without prior coordination with arpt manager and confirmation that ARFF is avbl prior to ldg or tkf. In the event of an air carrier diversion or other irregular ops events, aircraft opr should contact arpt manager 620-290-3810. Facility constraints include: lack of intl passenger processing facilities, ltd number of parking positions and ltd terminal space for passengers. Rwy 35 designated the calm wind rwy. Twr blind spot on the North Twy A hold bay.

AIRPORT MANAGER: 620-276-1190

WEATHER DATA SOURCES: ASOS 121.325 (620) 275-0803. LAWRS 1300-0300Z†.

COMMUNICATIONS: CTAF 118.15 UNICOM 122.95

RCD 122.2 (WICHITA RADIO)

Ⓜ **KANSAS CITY CENTER APP/DEP CON** 125.2

TOWER 118.15 (1300-0300Z†) **GND CON** 119.0

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Kansas City ARTCC at 913-254-8508.

AIRSPACE: CLASS D svc 1300-0300Z†; other times CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE GCK.

(VH) (H) **VORTACW** 113.3 GCK Chan 80 N37°55.14' W100°43.50' at fld. 2878/11E.

TACAN AZIMUTH unusable:

280°-010° blo 4,000'

280°-010° byd 11 NM

ILS 109.9 I-GCK Rwy 35. Class IB.

COMM/NAV/WEATHER REMARKS: FSS communications unreliable below 4400' at 40 NM.

WICHITA

H-5B, L-10G, 15C

IAP, AD

