
NORTH DAKOTA



TOMLINSON FLD (See NEW ROCKFORD on page 352)

TOWNER MUNI (D61) 1 NE 1484 B NOTAM FILE GFK	UTC-6(-5DT)	N48º21.55	′W100°23.74′		TWIN CITIES
RWY 03-21: 3080X150 (TURF) RWY 03: Road.	0.3% up NE				
RWY 16-34: 2932X100 (TURF) RWY 16: Road.	LIRL				
RWY 34: Road.					
 SERVICE: LGT ACTIVATE LIRL Rwy 16–34—CTAF. Dusk-dawn. AIRPORT REMARKS: Unattended. Confirm winter conditions after snowstorm with arpt manager 701–537–5137 or 701–537–3519. Rwy 03 has 140' water tower 2000' from thld 600' left of extended centerline. 3' ditch southeast end Rwy 16–34 and southwest end Rwy 03–21. Rwy 03–21 has 5' rwy visibility sight clearance violation. Rwy 03–21 marked 3' wooden red markers on ends and intersection. Rwy 16–34 marked 3' wooded red markers on ends and intersection. Rwy 16–34 marked 3' wooded red markers on ends and intersection. AIRPORT MANGER: (701) 537-3519 					
HELIPAD H1: H30X30 (CONC)	• •	• •	•••	• • •	•••
TRULSON FLD (See PLAZA on page	ge 355)				
TURTLE LAKE MUNI (91N) 1 1916 NOTAM FILE GFK RWY 08-26: 3148X120 (TURF) SERVICE: LGT ACTIVATE LIRL F	SW UTC–6(–5 LIRL 0.5% u ™y 08–26—CTA	ρE	0.58′W100°55.	00 <i>′</i>	TWIN CITIES
AIRPORT REMARKS: Unattended. Co 701–220–0707. Deer and wi	Idlife on and in vic	inity of arpt. R	wy 08–26 sfc gras	s soft when wet. Rwy 08	
50' out from thid. Rwy 08–2 AIRPORT MANAGER: (701) 516-382 COMMUNICATIONS: CTAF/UNICOM 122	26	irkeu with yell	ow tires around ig	15.	
			400 5500		

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.