

BOARDMAN (M50) 4 SW UTC-8(-7DT) N45°48.89' W119°49.23'

396 B NOTAM FILE MMV

RWY 04-22: H4200X100 (ASPH) S-30 MIRL 0.7% up SW**RWY 22:** Rgt tfc.**SERVICE:** LGT ACTIVATE MIRL Rwy 04-22-122.9.**AIRPORT REMARKS:** Unattended. Telephone avbl. Twy edge marked with blue reflectors. Rwy 04-22 cntrln in poor cond due to fading.**AIRPORT MANAGER:** 541-481-7678**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PDT.**PENDLETON (VH) (H) VORTACW** 114.7 PDT Chan 94 N45°41.91'
W118°56.32' 267° 37.7 NM to fld. 1575/14E.

VOR unusable:

057°-066° byd 40 NM

067°-078° byd 40 NM blo 29,000'

096°-106° byd 40 NM blo 8,300'

096°-106° byd 48 NM blo 18,000'

107°-117° byd 40 NM


118°-128° byd 40 NM blo 12,000'

118°-128° byd 75 NM

129°-207° byd 40 NM

SEATTLE

L-13A

**BROOKINGS** (BOK)(KBOK) 1 NE UTC-8(-7DT) N42°04.44' W124°17.39'

462 B NOTAM FILE BOK

RWY 12-30: H2901X60 (ASPH) S-11 MIRL 0.9% up NW**RWY 12:** PAPI(P2L)—GA 4.0° TCH 40'. Trees. Rgt tfc.**RWY 30:** PAPI(P2L)—GA 3.0° TCH 45'. Trees.**SERVICE:** FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 12-30 and PAPI Rwy 12 and Rwy 30—CTAF.
AIRPORT REMARKS: Unattended. Deer and elk invof arpt gnds. Arpt rot bcn lgt beam obscured by taller trees northeast-southeast quadrant.**AIRPORT MANAGER:** (541) 254-4278**WEATHER DATA SOURCES:** AWOS-3PT 132.025 (541) 412-8682.**COMMUNICATIONS:** CTAF/UNICOM 122.8

SEATTLE CENTER APP/DEP CON 124.85

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

KLAMATH FALLS

IAP