

FERNLEY**SAMSARG FLD** (N58) 3 S UTC-8(-7DT) N39°33.59' W119°14.56'

SAN FRANCISCO

4346 B NOTAM FILE RNO

L-9A

RWY 15-33: H3974X40 (ASPH)**RWY 15:** Rgt tfc.**RWY 33:** Hill.**RWY 05-23:** 2750X30 (GRVL-DIRT)**RWY 05:** Road.**RWY 23:** Hill.

AIRPORT REMARKS: Attended Mon-Fri 1500-0300Z±. Horse and cattle frqly on and invof rwys and twys. Rwy 05-23 eff gradient 4 percent W; dep Rwy 05 and arr Rwy 23 due to slp. Rwy 15-33 2-4' ditches in the pri sfc and rwy safety area parallel to Rwy 10 ft from rwy edge. Rwy 15-33 eff gradient 2 percent S. Rwy 05-23 mnt wet sx rwy conds—amgr. 1740' ovrn NW of Rwy 15 end not arpt property; may be mistaken for dsplcd thr. Arpt frqly clsd for model acct; remote acct ops on and invof arpt, rdo use encouraged. Hel trg rstrd to paved rwy ends; limit taxi and hover prac to ramp areas.

AIRPORT MANAGER: 775-471-7302**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc NorCal Apch at 916-361-0596.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RNO.**HAZEN (L) (L) VORTAC** 114.1 HZN Chan 88 N39°30.98' W118°59.86' 266° 11.7 NM to fld. 4086/17E.

VOR portion unusable:

300°-320° byd 30 NM blo 9,500'

FLYING M RANCH (See YERINGTON on page 413)**GABBS** (GAB)(KGAB) 4 NW UTC-8(-7DT) N38°55.34' W117°57.51'

LAS VEGAS

4699 NOTAM FILE RNO

RWY 09-27: 5950X65 (DIRT) 0.9% UP W**RWY 16-34:** 2650X75 (DIRT) 0.9% UP N**SERVICE:** LGT Arpt unlgtd; bcn lgt OTS indefly.

AIRPORT REMARKS: Unattended. No line of sight between Rwy 09-27 and Rwy 16-34. Jet actv N edge of tfc pat. Arr Rwy 09, dep Rwy 27, wind pmtg. Rwy 09-27 and Rwy 16-34 thr and edge mkd with reflectors. Rwy 09-27 and Rwy 16-34 thr and edge marked with reflectors; Rwy 09-27 and Rwy 16-34 reflective rods 240 ft fm EOR.

AIRPORT MANAGER: 775-751-6270**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Oakland ARTCC at 510-745-3380.**GOLDFIELD****GOLDFIELD** (I A8) 1 N UTC-8(-7DT) N37°43.32' W117°14.18'

LAS VEGAS

5616 NOTAM FILE Not insp.

RWY 01-19: 3150X37 (GRVL)**RWY 01:** Hill.**RWY 19:** Sign. Rgt tfc.**SERVICE:** LGT SS-SR

AIRPORT REMARKS: Unattended. Call for conditions 702-509-0059 or AMGR. Ngt ops discouraged; mts all quads. Gnd north of Rwy 19 thr slopes down 10' with gulleys left and right; powerlines east of rwy. EMS heli adj to Rwy 01 thr. Arr uphill Rwy 19; dep downhill Rwy 01. Rwy 01 and 19 thld marked with white tires. 1' berms around all rwys. Rwy 19 30' drop 200' fm thr left of cntrln.

AIRPORT MANAGER: 661-758-3009**COMMUNICATIONS:** CTAF 122.9

• • • • •
HELIPAD H1: H100X100 (CONC) RWY LGTS(NSTD)

LIDA JUNCTION (ØL4) 14 S UTC-8(-7DT) N37°29.51' W117°11.31'

LAS VEGAS

4684 NOTAM FILE RNO

RWY 18-36: 6100X80 (DIRT) 0.9% up N

AIRPORT REMARKS: Unattended. Rwy 18-36 ncntrld vehicle & wildlife invof rwy. 30 ft unlgt pole 408 ft fm Rwy 18 thr on extdd cntrln. Rwy 18-36 thr, tdz, and edges mkd with tires.

AIRPORT MANAGER: (775) 485-3406**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Nellis Apch at 702-652-4172.