

MONROE**CHARLOTTE/MONROE EXEC** (EQY)(KEQY) 5 NW UTC-5(-4DT) N35°01.04' W80°37.32'**CHARLOTTE**

683 B LRA NOTAM FILE EQY

H-9B, 12G, L-25D, 36E**RWY 05-23:** H7001X100 (ASPH) S-35, D-68.5 HIRL 0.3% up SW**IAP****RWY 05:** MALSR. PAPI(P4L)—GA 3.0° TCH 46'. Trees.**RWY 23:** REIL. PAPI(P4L)—GA 3.0° TCH 40'. Trees.**SERVICE:** S4 **FUEL** 100LL, JET A1+ **OX** 3, 4 **LGT** Actvt MALSR Rwy 05; REIL Rwy 23; HIRL Rwy 05-23—CTAF. All lights oper dusk-0500Z‡. After 0500Z‡, actvt—122.7. PAPI Rwy 05 & 23 oper consly.**AIRPORT REMARKS:** Attended 1200-0000Z‡. Deer, wildlife, and birds on and invof arpt. Fuel 24 hr credit card svc avbl. Arpt phone number 704-226-2300. Right side of Twy A at Rwy 23 has steep shoulder drop-off btn rwy and Twy A.**AIRPORT MANAGER:** 704-282-4731**WEATHER DATA SOURCES:** ASOS 135.775 (704) 283-5185.**COMMUNICATIONS:** CTAF/UNICOM 122.7Ⓡ **CHARLOTTE APP/DEP CON** 120.05**CLNC DEL** 132.55**CLEARANCE DELIVERY PHONE:** For CD ctc Charlotte Apch at 704-359-0241.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CLT.(L) (L) **VORW/DME** 115.0 CLT Chan 97 N35°11.42'
W80°57.11' 127° 19.3 NM to fld. 732/5W.

DME portion unusable:

015°-050° byd 25 NM blo 3,000'

050°-100° byd 25 NM blo 2,500'

185°-202° byd 15 NM


203°-220°

270°-350° byd 20 NM blo 5,000'

VOR/DME controlled by Charlotte ATCT

VOR unusable:

203°-220°

ILS/DME 109.75 I-EQY Chan 34(Y) Rwy 05. Class IA. LOC unmonitored 2200-1300Z‡. LOC unusable byd 30° left of course.**MONTGOMERY CO** (See STAR on page 356)**MOORE CO** (See PINEHURST/SOUTHERN PINES on page 341)