

WAINWRIGHT**WAINWRIGHT** (AWI)(PAWI) 1 SE UTC-9(-8DT) N70°38.28' W159°59.69'


CAPE LISBURNE

45 B NOTAM FILE AWI

H-1A, L-4I

RWY 06-24: 4494X110 (GRVL) MIRL

IAP

RWY 06: REIL. PAPI(P4L)—GA 3.0° TCH 31'. Antenna.**RWY 24:** REIL. PAPI(P4R)—GA 3.0° TCH 30'.**SERVICE:** LGT ACTVY REIL Rwy 06 and Rwy 24, PAPI Rwy 06 and Rwy 24, MIRL Rwy 06-24—CTAF.**AIRPORT REMARKS:** Unattended. Rwy cond unmnt; rcmd visual insp prior to use. Rwy 06-24, 40 ft twr 500 ft N of rwy. Birds on and invof arpt. Ramp and twy sfc soft; ruts and ponding psbl. NOTE: See Notices—Drone Activity at Coastal Airport Launch Sites.**AIRPORT MANAGER:** 907-852-0489**WEATHER DATA SOURCES:** ASOS 132.25 (907) 763-8881. (WX CAM)**COMMUNICATIONS:** CTAF 122.8**WAINWRIGHT RCO** 122.5 (BARROW RADIO)**ANCHORAGE CENTER APP/DEP CON** 135.3**RADIO AIDS TO NAVIGATION:** NOTAM FILE AWI.**NDB (HW)** 338 UKK N70°38.26' W160°00.56' at fld. 38/12E.**COMM/NAV/WEATHER REMARKS:** Barrow FSS—1-800-779-7709. Local call to Barrow FSS dial 907-852-2511. For a toll free call to Fairbanks dial 1-866-248-6516.**WAINWRIGHT AS** (AKØ3)(PAWT) PVT 0 N UTC-9(-8DT) N70°36.80' W159°51.62'

CAPE LISBURNE

35 B NOTAM FILE BRW Not insp.

L-4I

RWY 03-21: 3000X100 (GRVL) MIRL**RWY 03:** REIL. Rgt tfc.**RWY 21:** REIL.**SERVICE:** LGT Bcn on consly.**AIRPORT REMARKS:** CLOSED to public; Bureau of Land Management (BLM) facility. Caution: Rwy not mntnd; rcmd visual insp prior to ldg. Mult soft spots; dirt & grvl on rwy.**AIRPORT MANAGER:** (907) 382-4199**COMMUNICATIONS:** CTAF 126.2**WAINWRIGHT VILLAGE** N70°38.26' W160°00.56' NOTAM FILE AWI.

CAPE LISBURNE

NDB (HW) 338 UKK at Wainwright. 38/12E.

L-4I