

MASSENA INTL-RICHARDS FLD (MSS)(KMSS) 2 E UTC-5(-4DT) N44°56.17' W74°50.71'**MONTREAL**

221 B AOE ARFF Index—See Remarks NOTAM FILE MSS

H-11C, 12K, L-32G**RWY 05-23:** H5601X100 (ASPH-GRVD) S-30, D-50, 2D-76**IAP**

PCN 18 F/C/X/T HIRL 0.3% up NE

RWY 05: REIL. PAPI(P4L)—GA 3.0° TCH 55'. Pole.**RWY 23:** PAPI(P4L)—GA 3.0° TCH 43'.**RWY 09-27:** H4000X100 (ASPH-GRVD) S-30, D-50, 2D-76 MIRL**RWY 09:** REIL. Trees.**RWY 27:** REIL. PAPI(P4L)—GA 3.0° TCH 35'.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 05:** TORA-5601 TODA-5601 ASDA-5601 LDA-5601**RWY 09:** TORA-4000 TODA-4000 ASDA-4000 LDA-4000**RWY 23:** TORA-5601 TODA-5601 ASDA-5601 LDA-5601**RWY 27:** TORA-4000 TODA-4000 ASDA-4000 LDA-4000**SERVICE:** S1 **FUEL** 100LL, JET A **LGT** ACTIVATE REIL Rwy 05, Rwy 09 and Rwy 27, PAPI Rwy 23 and Rwy 27, HIRL Rwy 05-23, MIRL Rwy 09-27 and twy lgts—CTAF. PAPI Rwy 05 opr consly.**AIRPORT REMARKS:** Attended Mon-Fri 0900-2200Z†. Sat-Sun 1200-1300Z†. Birds and deer on and in/ov arpt. Frequent concentration of seagulls and Canada geese on and in/ov arpt particularly during poor wx periods. Class II, ARFF Index A. Index A coverage avbl durg atndc hrs. For emergs outside of atndc hrs, call St Lawrence emerg svc at 911. PPR 24 hrs for air carrier ops with more than 30 passenger seats, call arpt manager 315-769-7605. 421' lgt/marked twr 6000' south of arpt. Rwy conditions reported during normal hrs of ops. Caution NVD ops conducted periodically in arpt tfc pattern area. Mil hel training on and in/ov arpt. Rwy 05 first 50 ft not grvd. Rwy 09 first 50 ft not grvd. Rwy 27 first 50 ft not grvd. Overnight acft parking avbl at terminal apron. After attendance hrs vehicle and pedestrian access to FBO apron and hangar only avbl with key card for automatic gate. Commuter acft secure area clsd to general aviation acft clearing customs. Parking avbl to right of terminal bldg. Flight Notification Service (ADCUS) avbl. Ldg fee.**AIRPORT MANAGER:** 315-769-7429**WEATHER DATA SOURCES:** ASOS 128.075 (315) 764-0481.**COMMUNICATIONS:** CTAF/UNICOM 123.0

RCO 122.2 (BURLINGTON RADIO)

® **BOSTON CENTER APP/DEP CON** 135.25**CLEARANCE DELIVERY PHONE:** For CD if una to ctc on FSS freq, ctc Boston ARTCC at 603-879-6859.**AIRSPACE:** CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MSS.(H) **TACAN** Chan 88 MSS (114.1) N44°54.87' W74°43.36' 298° 5.4 NM to fld. 198/14W.**MISSE NDB (LOMW)** 278 MS N44°51.25' W74°54.95' 045° 5.8 NM to fld. 245/14W.

ILS 108.7 I-MSS Rwy 05. Class IE. LOM MISSE NDB. LOM unmonitored.

**MATTITUCK** (21N) 1 SE UTC-5(-4DT) N40°59.22' W72°31.15'**NEW YORK**

30 NOTAM FILE ISP

COPTER**RWY 01-19:** H2200X60 (ASPH)**RWY 01:** Trees.**RWY 19:** Trees.**AIRPORT REMARKS:** Unattended. Call amgr for pmsn to lnd. Deer on and in/ov arpt. All training ops, tkf and ldg practice and ngt ops are prohibited. Rwy 19, extensive pavement rutting at centerline, 240'-350' from thld. Segmented circle has no tfc pat indicator.**AIRPORT MANAGER:** 631-445-4348**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc New York Apch at 516-683-2449.