Z	
FISHERMANS BAY SPB (81W) 1 N UTC8(-7DT) N48°30.99′ W122°55.08′ 00 NOTAM FILE SEA	SEATTLI
WATERWAY 05W-23W: 3000X150 (WATER)	
WATERWAY 05W: Rgt tfc. SEAPLANE REMARKS: Unattended. Avoid overflights of houses on surrounding land. No step taxi in bay. Be	ware of boats
anchored in seaplane ldg area.	ware of boats
AIRPORT MANAGER: 360-468-4116 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.	
LOPEZ ISLAND (S31) 3 N UTC-8(-7DT) N48°29.04' W122°56.26' 209 B NOTAM FILE SEA	SEATTLI
RWY 16–34: H2905X61 (ASPH–GRVD) S–12.5 MIRL 1.6% up N	
RWY 16: REIL. PAPI(P2L)-GA 4.0° TCH 43'. Trees. Rgt tfc.	
RWY 34: REIL. PAPI(P2L)—GA 4.0° TCH 33'. Trees.	
AIRPORT REMARKS: Unattended. Rwy 16–34 soft shoulders and thids. AIRPORT MANAGER: 360-468-4116	
COMMUNICATIONS: CTAF 128.25	
CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.	
LOST RIVER (See MAZAMA on page 245)	
LOWER GRANITE STATE (See COLFAX on page 226)	
LOWER MONUMENTAL STATE (See KAHLOTUS on page 239)	
LYNDEN MUNI/JANSEN FLD(38W) 1 N UTC-8(-7DT) N48°57.35´ W122°27.49´	SEATTLE
106 B NOTAM FILE SEA <b>RWY 08–26</b> : H2425X40 (ASPH) S–12 RWY LGTS(NSTD)	
<b>RWY 08:</b> PAPI(P2L)—GA 3.0° TCH 15′. Thid dspicd 262′. Trees.	
RWY 26: PAPI(P2R)—GA 6.0° TCH 15'. Thild dsplcd 422'. Trees.	
RUNWAY DECLARED DISTANCE INFORMATION	
RWY 08: LDA-2163 RWY 26: Tora-2425 LDA-2003	
SERVICE: FUEL 100LL LGT Use 3 clicks to ACTVT MIRL Rwy 08–26 and rotating bcn—CTAF.	
AIRPORT REMARKS: Unattended. Automated credit card system for fuel. Structures and trees in pri sfcs. Ex	posed ditch Rwy
08–26. Avoid night Indgs to Rwy 26—night Indgs should be performed on Rwy 08—winds permittin	-
Igts; Rwy 08 thr Igts located 134 ft prior to dsplcd thr. Rwy 08 thr relctd 155 ft for ngt opns; Rwy 2 for ngt opns; 1871 ft Igtd at night. No white/red Igts past dsplcd thld. Run–ups not permitted on Rw	
taxiway. Acft with 40 ft wing span adzd to back taxi and not to use west twy. Fly PAPI on all approa	
WSDOT kiosk lctd at fuel stn. Bicycles avbl in pilot 's lounge.	-
AIRPORT MANAGER: 360-354-3446	
COMMUNICATIONS: CTAF 122.9 Victoria terminal App/dep con 132.7 290.8 604–586–4560	
COMM/NAV/WEATHER REMARKS: Automated UNICOM; 3 clicks.	
MANSFIELD (8W3) 0 E UTC-8(-7DT) N47°48.56′W119°38.22′	SEATTL
2272 B NOTAM FILE SEA	
RWY 03-21: H2575X46 (ASPH) LIRL RWY 03: Road.	
RWY 21: Road.	
RUNWAY DECLARED DISTANCE INFORMATION	
RWY 03: TORA-2400 RWY 21: TORA-2400	
SERVICE: LGT Rwy 03–21 no rwy lgts northside of Rwy 21 end to midfield. Bcn tempo OTS.	
	is widespread, oper
AIRPORT REMARKS: Unattended. Possible turbulence from grain elevators north side of arpt. Rwy 03–21 ha	
AIRPORT REMARKS: Unattended. Possible turbulence from grain elevators north side of arpt. Rwy 03–21 ha unsealed cracks and joints. NW prkg has steep dropoff. Rwy 03–21 markings faded. Pilots bring own r	opes. Lgtd wind tee
AIRPORT REMARKS: Unattended. Possible turbulence from grain elevators north side of arpt. Rwy 03-21 ha	opes. Lgtd wind tee

MARTIN FLD (See COLLEGE PLACE on page 227)