45

LOWER LOON CREEK (C53) 30 SW UTC-7(-6DT) N44°48.52′ W114°48.52′ 4200 NOTAM FILE BOI

RWY 16-34: 1200X25 (TURF-DIRT) 1.2% up S

RWY 16: Tree.

AIRPORT REMARKS: Unattended. Recommend land Rwy 16, dep Rwy 34 when wind cond allow. No winter maint. Rwy not marked. Arpt lctd on a plateau 50' to 75' aby the river. Lctd in narrow winding river canyon. Rodent activity adi both sides of rwy. Stock and big game animals invof rwy.

AIRPORT MANAGER: 208-756-2271

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

MARBLE CREEK (ID8) 36 WNW UTC-7(-6DT) N44°46.41′ W114°59.12′ GREAT FALLS

4685 NOTAM FILE BOI

RWY 04-22: 1160X20 (DIRT-TURF)

RWY 04: Hill. RWY 22. Trees

AIRPORT REMARKS: No winter maint. Use at own risk; rwy is very shrt and very challenging. Rwy is not mkd. Trees & trrn on apch to both rwy ends. Big game animals & stock on and in vcnty of rwy. Rwy is a very shrt & challenging strip due to hi rsg trrn & trees; rcmd for use only by experienced & properly trnd backcounty pilots with the right eqpt suitable for this environment. Due to hi density alt, ery mrng & late eve ops is rcmd durg summer months. Apt lctd in dp canyon and is srnd by hi, timbered, mtous trrn. Rwy end 04 sfc cond is dominated by soft sandy soil for the first 350 ft-400 ft.

AIRPORT MANAGER: 208-756-2271

COMMUNICATIONS: CTAF 122 9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 1-801-320-2568.

UPPER LOON CREEK USFS (U72) 26 NW UTC-7(-6DT) N44°35.49′ W114°49.39′

5500 NOTAM FILE BOI

RWY 04-22: 2500X75 (TURF-DIRT)

RWY 04. Tree

AIRPORT REMARKS: Unattended, Recommend land Rwy 22, tkf Rwy 04 when wind cond permit. Trees and high terrain on both ends of Rwy 04-22, requires a steep approach. Rwy 04-22 numerous additional obstructions on apch to both rwy ends. No winter maint. Recommended for experienced mountain pilots only. Rwy 04-22 edges and thlds marked with white

AIRPORT MANAGER: 208-879-4101 COMMUNICATIONS: CTAF 122 Q

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

CHAMBERLAIN GUARD STATION

CHAMBERLAIN USFS (U79) 0 E UTC-7(-6DT) N45°22.74′ W115°11.81′

GREAT FALLS

GREAT FALLS

5765 NOTAM FILE BOI

RWY 07-25: 4100X200 (TURF-DIRT)

PWV 07. Trace

RWY 25. Tree

RWY 15-33: 2700X140 (TURF)

RWY 15. Trees

RWY 33: Trees.

AIRPORT REMARKS: Unattended. Exty rodent activity on both rwys. Arpt subi tempo CLOSED ery spring to soft rwys. Rwy end 25—first 300 ft of sfc is rough. Rwy 15-33 rough and uneven sfc. Rwy 07-25 and Rwy 15-33 thrs mkd and rwys outlined with yellow rocks—barely vsb. Rwy 15-33 has +2' pipe and -2' ditch across rwy North of Rwy 07-25 int; first 300' of Rwy 33 clsd. +70 ft trees adj to all rwy edges. No fone avbl at arpt. Private Stone Breaker Arpt lctd 1 NM NE of Chamberlain USFS.

AIRPORT MANAGER: 208-634-0600

COMMUNICATIONS: CTAF 122 9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

CHAMBERLAIN USFS (See CHAMBERI AIN GUARD STATION on page 45)