

RALEIGH**TRIPLE W** (5W5) 11 SW UTC-5(-4DT) N35°37.22' W78°42.02'**CHARLOTTE**

244 B NOTAM FILE RDU

L-35B, 36F

RWY 16-34: H3004X40 (ASPH) LIRL(NSTD) 0.3% up N**RWY 16:** Trees.**RWY 34:** Trees.**SERVICE:** LGT Dusk—0500Z†. Actvt LIRL—CTAF. No CTAF prior to dusk. Rwy 16-34 NSTD LIRL. Rwy 16-34 lgts 15' from edge of rwy. No thld lgts. Twy not lgtd.**AIRPORT REMARKS:** Attended irregularly. Deer on and invof arpt. Numerous unlighted obstructions invof arpt. Night or tsnt tfc ldfs not recommended. Rwy 16-34 PAEW parallel twy. All acct over 6500 lbs. prohibited. Tower (500 AGL/826' MSL) approximately 1.75 NM NW of arpt. Be alert for rising terrain all quadrants. Rwy 16-34 has 4' dropoff 20' from pavement edge all sides. 4 ft dropoff twy edge both sides—south end. Be alert 1000' of twy North end Rwy 16 unusbl due to erosion under pavement. CAUTION: vehicles on or invof Rwy 16-34. Rwy 16-34 heavy vegetation in cracks. Rwy 16-34 markings nonexistent.**AIRPORT MANAGER:** (919) 971-3718**COMMUNICATIONS:** CTAF/UNICOM 122.7**CLEARANCE DELIVERY PHONE:** For CD ctc Raleigh Apch at 919-380-3144.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RDU.**RALEIGH/DURHAM (H) (H) VORTACW** 117.2 RDU Chan 119 N35°52.35' W78°47.00' 174° 15.6 NM to fld. 4299W.**RALEIGH EAST** (See KNIGHTDALE on page 320)**RALEIGH EXEC JETPORT AT SANFORD-LEE CO** (See SANFORD on page 347)**RALEIGH RGNL AT PERSON CO** (See ROXBORO on page 345)**RALEIGH-DURHAM INTL** (See RALEIGH/DURHAM on page 342)